





### General information

Make	RENAULT
Model	KANGOO AUTHENTIQUE 16V E4
Colour	Grey
Year of manufacture	2008
Top speed	101 mph
0 - 60 mph	12.4 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	95 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	190 g/km
CO2 label	J







# Internet history


Entry	1

Date Pictures 2021-09-30

16

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-21
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	44
Total items failed	7

MOT #17	2023-09-19 15:49
MOT test number	743483619719
Result	✓ Passed
Next expiry date	2024-09-21

MOT #16	2022-09-22 16:47
MOT test number	435988955473
Result	✓ Passed

MOT #15	2021-07-14 15:	11
MOT test	number 3632428008	06
Result	✓ Pass	ed
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn outer edge/cracking (5.2.3 (e))	
Advice	Central Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both front disc (1.1.14 (a) (ii)	)
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #14		2021-07-14 09:54
MOT test	number	692469143439
Result		🗙 Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn outer edge/crack	ing (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both front dis	sc (1.1.14 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
DANGER	<b>OUS</b> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Central Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #13	2020-06-16 10:12
MOT test number	122431657849
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))	

MOT #12		2019-06-10 12:46
MOT test	number	291958782052
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #11		2019-06-10 09:36
MOT test	number	291232734126
Result		🗙 Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Offside Front Drive shaft flexible coupling excessively deteriorated (6.1.7 (d) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
MAJOR	Windscreen washer not working (3.5 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10		2018-05-16 10:11
MOT test	number	583286494818
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	

MOT #9	2018-05-15 09:52
MOT test number	353839776537
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Fail Central Exhaust has a major leak of exhaust gases (7.1.2)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	



🗸 Passed



MOT #8	2016-12-06 11:50
MOT test number	665043779508
Result	✓ Passed
MOT #7	2015-12-16 10:53
MOT test number	670542550417
Result	✓ Passed
MOT #6	2014-12-11 16:02
MOT test number	566435244373

Result

MOT #5	2014-12-10 17:35
MOT test number	447174844438
Result	🗙 Failed
<b>Fail</b> Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	

MOT #4		2013-08-16 10:20
MOT test	number	457178923273
Result		✓ Passed
Advice	Nearside Brake pipe slightly corroded (3.6.B.2c)	
Advice	Offside Brake pipe slightly corroded (3.6.B.2c)	

MOT #3		2012-09-21 11:35
MOT test	number	228125062268
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	



GX58LBG
report date: 2024-03-29

MOT #2	2012-09-13 13:03
MOT test number	609177852287
Result	🗙 Failed
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
FailRear Exhaust has a major leak of exhaust gases (7.1.2)	
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Side repeater not working (1.4.A.2c)	

MOT #1	2011-11-04 11:00
MOT test number	877828401304
Result	✓ Passed
Notice Drivers sun visor missing	
Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	✓ MOT Expires: 21 September 2024
Tax status	Valid until 1 October
Days left	154
MOT expiry date	21 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	
***********	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Rule sizes	





#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GX58LBG report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-12-19
Last registration	2023-09-19
Complete history	See info



Registration #1	2008-12-19	18 mi
Registration #2	2011-11-04	18.179 mi
Registration #3	2012-09-13	22.929 mi
Registration #4	2012-09-21	23.062 mi
Registration #5	2013-08-16	26.578 mi
Registration #6	2014-12-10	29.338 mi
Registration #7	2014-12-11	29.338 mi
Registration #8	2015-12-16	31.684 mi
Registration #9	2016-12-06	33.031 mi
Registration #10	2018-05-15	34.667 mi
Registration #11		11.777 mi
Registration #12		11.777 ma
Registration #12 Registration #13		11.777 es
-		11,117 es
Registration #13		01,000 es
Registration #13 Registration #14		01,000 es
Registration #13 Registration #14 Registration #15		01,007 46 01,007 46 01,007 46 01,007 46 01,007 46 01,007 46
Registration #13 Registration #14 Registration #15 Registration #16		01,000 44 01,000 44 01,000 44 01,000 44 01,000 44 01,000 44 01,000 44





#### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2605 mm
Max. allowed weight	1645 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	
	5
Number of seats	5 5

**Engine number** 

D025857