





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TIGUAN R LINE TDI 4MOTION
Colour	Silver
Year of manufacture	2010
Top speed	125 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	33.6 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	Н



CarCheck.co.uk page 1/13



DE10PNK report date: 2024-03-28

Internet history

Entry 2

Date 2022-11-17


Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-14
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-04-23
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #14	2024-04-23 07:56
MOT test number	269051127807
Result	✓ Passed
Next expiry date	2025-04-23

MOT #13		2023-04-24 12:18
MOT test i	number	963069548796
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12		2022-03-18 15:29
MOT test	number	511138249581
Result		✓ Passed
Advice	Brake disc worn, but not excessively Both front (1.1.14 (a) (i))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weaker	ned (1.1.14 (a) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #11 2022-03-15 17:45

MOT test number 894508819183

Result X Failed

Advice Brake disc worn, but not excessively Both front (1.1.14 (a) (i))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Minor Anti-roll bar linkage ball joint dust cover severely deteriorated Both front (5.3.4 (b) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2020-10-31 10:56

MOT test number 201706392428

Result \square Passed

Advice Nearside Rear Outer Brake pad(s) wearing thin brake pad wearing thin close to 1.5mm limit. (1.1.13 (a) (ii))

MOT #9 2019-05-09 15:42

MOT test number 645943476682

Result

Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2019-05-09 14:50

MOT test number 509641538144

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7 2018-05-05 09:46

MOT test number 484846433800

MOT #6 2017-05-05 08:56

MOT test number 802236941764

Result
✓ Passed

Advice Front tyres starting to wear low in places

MOT #5 2016-05-14 12:24

MOT test number 851052801738

Result ✓ Passed

MOT #4 2015-04-24 15:21

MOT test number 247904815499

Result \rightarrow Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2014-05-02 11:36

MOT test number 529292824177

Result ✓ Passed

MOT #2 2014-05-02 11:36

MOT test number 435932624176

Result X Failed

Pass with rectification Offside Headlamp aim too high (1.8)

Pass with rectification Nearside Headlamp aim too high and too far to the right. (1.8)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Notice Offside front wishbone rear bush is starting to split.

Notice Nearside front wishbone rear bush is starting to split.

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	23 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	
Туре	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



DE10PNK report date: 2024-03-28

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-13
Last registration	2024-04-23
Complete history	See info



Registration #1	2010-05-13	10 mi
Registration #2	2013-05-08	32.638 mi
Registration #3	2014-05-02	45.413 mi
Registration #4	2015-04-24	56.990 mi
Registration #5	2016-05-14	62.534 mi
Registration #6	2017-05-05	68.418 mi
Registration #7	2018-05-05	75.024 mi
Registration #8	2019-05-09	81.732 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 12/13



DE10PNK report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Adult	87%
Children	79%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1609 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
CarChack co.uk	nago 13/1

CarCheck.co.uk page 13/13

Engine number

CBB 328529