



RENAULT

DK56JZD

report date: 2024-03-29

General information

| | |
|---------------------|--------------------------|
| Make | RENAULT |
| Model | MEGANE DYNAMIQUE VVT 111 |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 124 mph |
| 0 - 60 mph | 11.8 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 110 BHP |
| Max. torque | 148 Nm at 3.750 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.1 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |



**MOT history**

| | |
|-------------------------|---|
| MOT #19 | 2021-12-06 14:39 |
| MOT test number | 141956929158 |
| Result | ✓ Passed |
| Next expiry date | 2022-12-05 |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) |

| | |
|------------------------|---|
| MOT #18 | 2021-12-06 10:50 |
| MOT test number | 961190422828 |
| Result | ✗ Failed |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| Fail | Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) |

| | |
|------------------------|---|
| MOT #17 | 2020-12-02 17:18 |
| MOT test number | 501047843848 |
| Result | ✓ Passed |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) |

| | |
|------------------------|------------------|
| MOT #16 | 2019-12-06 18:53 |
| MOT test number | 543624044934 |
| Result | ✓ Passed |

**MOT #15** 2018-10-08 09:36**MOT test number** 216020963065**Result** ✓ Passed**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened N/S + O/S (1.1.14 (a) (ii))**Advice** Play in steering rack inner joint(s) N/S + O/S**Advice** Brake pad(s) wearing thin Front & Rear (1.1.13 (a) (ii))**MOT #14** 2018-10-08 09:36**MOT test number** 975193172262**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Brake pad(s) wearing thin Front & Rear (1.1.13 (a) (ii))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Pass with rectification** Front Position lamp not working N/S + O/S (4.2.1 (a))**Advice** Play in steering rack inner joint(s) N/S + O/S**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened N/S + O/S (1.1.14 (a) (ii))**MOT #13** 2017-09-21 13:54**MOT test number** 558185730336**Result** ✓ Passed**MOT #12** 2017-09-21 13:54**MOT test number** 583220526100**Result** ✗ Failed**Pass with rectification** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)**Pass with rectification** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

**MOT #11** 2016-09-26 11:03**MOT test number** 411263195343**Result** ✓ Passed**MOT #10** 2016-09-26 11:03**MOT test number** 327508772744**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #9** 2015-09-26 11:10**MOT test number** 343351204144**Result** ✓ Passed**MOT #8** 2015-09-26 11:10**MOT test number** 456923239777**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**MOT #7** 2014-06-03 11:37**MOT test number** 125714054126**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-05-15 13:14**MOT test number** 688135933181**Result** ✓ Passed**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Notice** N/S/F + O/S/F Steering Arm Has SLight Play**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-05-19 11:31**MOT test number** 648670942183**Result** ✓ Passed**MOT #4** 2011-05-18 16:42**MOT test number** 899008631167**Result** ✓ Passed**MOT #3** 2010-10-21 11:03**MOT test number** 294614390293**Result** ✓ Passed**Notice** Nail in offside front tyre**Notice** Rear tyres sidewalls have deteriorated**Notice** Blade in nearside rear tyre**MOT #2** 2009-09-30 14:49**MOT test number** 263423179287**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Nearside Rear Shock absorber has slight external damage to the casing (2.7.2a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



| | |
|-----------------|---|
| MOT #1 | 2009-09-30 12:05 |
| MOT test number | 833953179242 |
| Result | ✗ Failed |
| Fail | Rear registration plate character(s) formed using broken strokes (6.3.4e) |
| Fail | Rear registration plate font not substantially similar to the prescribed font (6.3.4d) |
| Advice | Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a) |
| Fail | Front registration plate character(s) formed using broken strokes (6.3.4e) |
| Fail | Front registration plate font not substantially similar to the prescribed font (6.3.4d) |
| Advice | Nearside Rear Shock absorber has slight external damage to the casing (2.7.2a) |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) |



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-03-29 |
| Current registration | |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | |
|-------------------|-----------------|
| Finance company | RENAULT FINANCE |
| Date of agreement | 01/01/2024 |
| Agreement type | FINANCE |
| Agreement term | 36 months |
| Agreement number | 123456789 |
| Contact info | 01234 567890 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2006-10-05 |
| Last registration | 2021-12-06 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-10-05 | 18 mi |
| Registration #2 | 2009-09-30 | 27.087 mi |
| Registration #3 | 2009-09-30 | 27.087 mi |
| Registration #4 | 2010-10-21 | 32.124 mi |
| Registration #5 | 2011-05-18 | 33.625 mi |
| Registration #6 | 2012-05-19 | 39.514 mi |
| Registration #7 | 2013-05-15 | 45.183 mi |
| Registration #8 | 2014-06-03 | 51.441 mi |
| Registration #9 | 2015-09-26 | 52.843 mi |
| Registration #10 | 2016-09-26 | 55.377 mi |
| Registration #11 | 2016-09-26 | 55.377 mi |
| Registration #12 | 2016-09-26 | 55.377 mi |
| Registration #13 | 2016-09-26 | 55.377 mi |
| Registration #14 | 2016-09-26 | 55.377 mi |
| Registration #15 | 2016-09-26 | 55.377 mi |
| Registration #16 | 2016-09-26 | 55.377 mi |
| Registration #17 | 2016-09-26 | 55.377 mi |
| Registration #18 | 2016-09-26 | 55.377 mi |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1698 mm |
| Height | 1366 mm |
| Length | 4028 mm |
| Wheel base | 2522 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1775 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 4 |

| | |
|---------------|---------|
| Engine number | D050625 |
|---------------|---------|