






report date: 2024-03-29

General information

Make	RENAULT	
Model	CLIO DYNAMIQUE NAV DCI	
Colour	Red	
Year of manufacture	2018	
Top speed	109 mph	
0 - 60 mph	12.9 seconds	
Gearbox	6 speed automatic	

Engine & fuel consumption

Power	89 BHP	
Max. torque	220 Nm at 1.750 rpm	
Engine capacity	1.461 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	72.4 mpg	
Consumption extra urban	85.6 mpg	
Consumption combined	80.7 mpg	
CO2 emission	92 g/km	
CO2 label	A	



CarCheck.co.uk page 1/11



CE18YWF

report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-03

Pictures 7

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date 2021-06-25

Pictures 7

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-04-05
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #6	2024-03-21 16:28
MOT test number 4632994	
Result	✓ Passed
Next expiry date	2025-04-05
Advice Front Brake disc worn, but not excessively Both front brake discs worn (1.1.14 (a) (i))	
Advice Rear Tyre slightly damaged/cracking or perishing Both rear tyres are cracking and perishing in the tread area and have side wall damage as well (5.2.3 (d) (ii))	
Advice Front Tyre worn close to legal limit/worn on edge Both front tyres wearing close to legal limit on both edges (5.2.3 (e))	
Advice Front Brake pad(s) wearing thin Front brake pads wearing thin (1.1.13 (a) (ii))	
Advice TPMS on on dash indicating tyres either under/over inflat	ed or needs resetting

MOT #5	2024-03-21 16:28	
MOT test number	932155613333	
Result	★ Failed	
Pass with rectification (a))	Windscreen washer provides insufficient washer liquid Washer bottle empty (3.5	
Advice Front Tyre worn both edges (5.2.3 (e))	close to legal limit/worn on edge Both front tyres wearing close to legal limit on	
Advice Front Brake pad	(s) wearing thin Front brake pads wearing thin (1.1.13 (a) (ii))	
Advice TPMS on on dash indicating tyres either under/over inflated or needs resetting		
Advice Front Brake disc worn, but not excessively Both front brake discs worn (1.1.14 (a) (i))		
	y damaged/cracking or perishing Both rear tyres are cracking and perishing in the ill damage as well (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



CE18YWF

report date: 2024-03-29

MOT #4	2023-04-01 10:00
MOT test number	700649079417
Result	✓ Passed
MOT #3	2022-04-01 12:19
MOT test number	335949029927
Result	✓ Passed
MOT #2	2021-04-06 10:00
MOT test number	484390247603
Result	✓ Passed
MOT #1	2021-04-06 10:00
MOT test number	686924372553
Result	★ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



obser of plates

laries scinces

Plate since

CE18YWF

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owners did this R have? Check it in the premium report and see all owner registrations. Download the full report here .	ENAULT
HARMANNA	

More int	o >
Plate changes	
See in this check if this RENAULT had different number plates.	

UK UK

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



CE18YWF

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-22
Last registration	2024-03-21
Complete history	See info



Registration #1	2018-05-22	18 mi
Registration #2	2021-04-06	8.527 mi
Registration #3	2021-04-06	8.527 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1448 mm
Length	4063 mm
Wheel base	2589 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number R018417