





report date: 2024-03-29

General information

Make	TOYOTA
Model	AURIS VVT-I ICON TOURING SPORTS
Colour	Grey
Year of manufacture	2016
Top speed	112 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	305 Nm at 4.400 rpm
Engine capacity	1.798 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption combined	65.3 mpg
CO2 emission	83 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history


Entry 2

Date 2021-07-12

Pictures 19

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date	2021-06-08

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-26
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	14
Total items failed	7

MOT #10		2024-04-19 10:17
MOT test number		133809375393
Result		√ Passed
Next expiry date		2025-04-26
Minor Windscreen dar	naged but not adversely affecting driver's view	v (3.2 (a) (i))
Advice Nearside Rear	Shock absorbers has light misting of oil (5.3.2	(b))
Advice Nearside Front	Tyre has a cut but not deep enough to reach t	the ply or cords (5.2.3 (d) (i))
Advice Offside Rear SI	hock absorbers has light misting of oil (5.3.2 (b	0))

MOT #9	2024-04-17 10:20
MOT test number	293373496088
Result	× Failed
Advice Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Fail Windscreen washer not working (3.5 (a))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5	5.2.3 (d) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

× Failed

MOT #8 2023-04-13 13:31

MOT test number 289303736041

Result \rightarrow Passed

Advice

Result

Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7 2023-04-13 13:31

MOT test number 876863529020

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2022-04-19 14:03

MOT test number 477705863933

Result ✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #5 2022-04-19 14:03

MOT test number 190459929189

Result × Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification Offside Headlamp aim too low (4.1.2 (a))

Pass with rectification Nearside Headlamp aim too low (4.1.2 (a))

MOT #4 2021-04-27 13:02

MOT test number 403532487822

Result \rightarrow Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT test number

441822357316

Result

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Pass with rectification (b) (ii))

Pass with rectification (b) (iii)

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #1	2019-05-08 09:40
MOT test number	262415304009
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	26 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.)TA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK C	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-05-23
Last registration	2024-04-19
Complete history	See info



Registration #1	2016-05-23	24 mi
Registration #2	2019-05-08	33.781 mi
Registration #3	2020-09-23	51.404 mi
Registration #4	2020-09-23	51.404 mi
Registration #5	2021-04-27	53.322 mi
Registration #6		0.00 44
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	68%
Safety systems	66%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1485 mm
Length	4595 mm
Wheel base	2600 mm
Kerb weight	1425 kg
Max. allowed weight	1815 kg

Additional information

Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 12/12

Engine number

2ZRV275260