

Ford



General information

Make	FORD
Model	FUSION 16V GHIA
Colour	Silver
Year of manufacture	2003
Top speed	104 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	157 g/km
CO2 label	G







Internet history

Entry 1

Date Pictures 2021-06-23

25

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-05-06
MOT pass rate	63 %
MOT passed	17
Failed MOT tests	10
Total advice items	31
Total items failed	20

МОТ #27	2024-04-25 16:06
MOT test number	746601191397
Result	Passed
Next expiry date	2025-05-06
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



MOT #26	2024-04-25 08:32
MOT test number	665446596469
Result	🗙 Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2)	(b))
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c	:))
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #25		2023-04-22 11:04
MOT test	number	315138611485
Result		✓ Passed
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously redu	ucing light output (4.1.4
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously re	educing light output (4.1.4

AJ53OBT

report date: 2024-03-29





MOT #24	2023-04-22 08:15
MOT test number	917217884953
Result	🗙 Failed
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively wor	rn (5.1.2 (b) (i))
Advice Offside Front Headlamp has a product on the lens but not seriously reducing (b))	light output (4.1.4
Fail Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively w	vorn (5.1.2 (b) (i))
Advice Nearside Front Headlamp has a product on the lens but not seriously reducin (b))	ng light output (4.1.4

MOT #23	2022-04-12 08:59
MOT test	number 244587851853
Result	✓ Passed
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing
arm bush	(5.3.4 (a) (i))
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing
arm bush	(5.3.4 (a) (i))

MOT #22	2021-05-07 10:33
MOT test number	423901113040
Result	✓ Passed
MOT #21	2021-05-07 10:32
MOT test number	851106562512
Result	🗙 Failed

Pass with rectificationNearside Front Position lamp adversely affected by the operation of anotherlamp (4.2.3 (c))





MOT #2	20	2017-02-20 15:02
MOT te	est number	437610889222
Result		✓ Passed
MOT #3	19	2017-02-20 11:09
MOT te	est number	727810589854
Result		🗙 Failed
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)	
Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)		
Fail	Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)	
Fail	Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)	

MOT #18	2016-02-15 14:04
MOT test number	911918753824
Result	✓ Passed
Advice Oil filter corroded and starting to leak	

MOT #17	2016-02-15 11:00
MOT test number	710758350509
Result	🗙 Failed
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Oil filter corroded and starting to leak	
Fail Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)	
Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)	

MOT #16	2015-02-23 08:39
MOT test number	645024255074
Result	✓ Passed





MOT #15	2015-02-23 08:39
MOT test number	239934355070
Result	🗙 Failed
Pass with rectification Offside Stop lamp not working (1.2.1b)	
MOT #14	2014-03-04 08:25
MOT test number	997513464066
Result	✓ Passed
MOT #13	2014-03-03 09:58
MOT test number	456602764091
Result	🗙 Failed
Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)	
	2013-03-13 12:27
	2013-03-13 12:27 536132073086
MOT #12	
MOT #12 MOT test number Result	536132073086
MOT #12 MOT test number Result	536132073086 ✓ Passed
MOT #12 MOT test number Result MOT #11	536132073086 ✓ Passed 2012-03-14 13:28
MOT #12 MOT test number Result MOT #11 MOT test number	536132073086 ✓ Passed 2012-03-14 13:28 967004772046
MOT #12 MOT test number Result MOT #11 MOT test number Result Notice Child seat fitted not allowing full inspection of adult belt	536132073086 ✓ Passed 2012-03-14 13:28 967004772046
MOT #12 MOT test number Result MOT test number Result	536132073086 ✓ Passed 2012-03-14 13:28 967004772046 ✓ Passed

	•	
Notice	Child seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	





MOT #9	2011-02-28 12:51
MOT test number	837979151008
Result	🗙 Failed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice Child seat fitted not allowing full inspection of adult belt	
Fail Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #8		2010-02-16 10:51
MOT test number		923827440027
Result		🗙 Failed
Advice Nearside Rear T	yre worn close to the legal limit (4.1.E.1)	
Pass with rectification	Centre Rear Stop lamp not working (1.2.1b)	
Advice Offside Front Ty	re worn close to the legal limit (4.1.E.1)	

MOT #7		2010-02-16 10:51
MOT test	number	670677540042
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

МОТ #6	2009-01-28 12:46
MOT test number	191088729467
Result	✓ Passed





MOT #5	2009-01-28 10:43
MOT test number	362768629058
Result	🗙 Failed
Fail Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)	
MOT #4	2008-01-29 16:18
MOT test number	810759628053
Result	✓ Passed
MOT #3	2007-02-22 14:37
MOT test number	404873557012
Result	✓ Passed
MOT #2	2006-10-19 11:19
MOT test number	972142696222
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	
MOT #1	2006-10-19 11:11

MOT test number	792662496205
Result	✓ Passed

Result



Tax & MOT check

Tax due: 1 January 2025	✓ Taxed	✓ MOT Expires: 6 May 2025	
Tax status			Valid until 1 January
Days left			247
MOT expiry date			6 May 2025
Full MOT history			<u>See MOT history</u>
Tax calculation			

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	 FE CO
Category	Lamp
Туре	
Damage 2	AMPLE
Damaye 2	C C C C
Date	
Category	 AMP
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-11-25
Last registration	2024-04-25
Complete history	See info



Registration #1	2003-11-25	13 mi
Registration #2	2006-10-19	24.596 mi
Registration #3	2006-10-19	24.596 mi
Registration #4	2007-02-22	25.237 mi
Registration #5	2008-01-29	35.413 mi
Registration #6	2009-01-28	39.467 mi
Registration #7	2009-01-28	39.467 mi
Registration #8	2010-02-16	41.746 mi
Registration #9	2011-02-28	43.653 mi
Registration #10	2011-02-28	43.653 mi
Registration #11	2012-03-14	51.391 mi
Registration #12	2013-03-13	54.449 mi
Registration #13	2014-03-03	58.155 mi
Registration #14	2014-03-04	58.155 mi
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.777 esi
Registration #20		11.777 esi
Registration #21		11.777 esi
Registration #22		11.777 est
Registration #23		11.777 esi
Registration #24		11.117 est
Registration #25		11.777 mi
Registration #26		11.117 est
CarCheck.co.uk		page 15/16





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1905 mm
Height	1467 mm
Length	3917 mm
Wheel base	2486 mm
Kerb weight	1085 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number CarCheck.co.uk	3Y36874