





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Grey
Year of manufacture	2010
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-20

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-11
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	22
Total items failed	2

MOT #13	2023-10-12 13:49
MOT test number	339749732511
Result	✓ Passed
Next expiry date	2024-10-11
Advice Front Suspension arm pin or bush worn but not resulting in excessive arm inner rear-most bushes * (5.3.4 (a) (i)) Advice Tyre worn close to legal limit/worn on edge *All Four Tyres Worn Slig R16 91V)* (5.2.3 (e))	

MOT #12	2022-10-05 09	9:05
MOT test	number 665028965	274
Result	✓ Pas	sed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #11	2021-09-13 13:33
MOT test number	823236250036
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice
Both front lower arms rear most bushes starting to split but no movement

Advice
Nearside Rear Tyre worn close to legal limit/worn on edge starting to wear thin on edges (5.2.3 (e))

Advice
Parking brake travel becoming high

Brake hose slightly deteriorated both rear (1.1.12 (b) (ii))

MOT #9 2019-10-22 07:55 **MOT** test number 987564634615 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre wearing low, 3mm (5.2.3 (e)) Advice Coolant level on min Advice Fuel tank exhaust shield loose Advice Front Exhaust mounting defective Exhaust mounting corroded/detached (6.1.2 (a)) Advice Nearside Front Tyre worn close to legal limit/worn on edge Tyre wearing low, 3mm + worn low on edges (205/55R16) (5.2.3 (e)) **Advice** Front exhaust flexy starting to deteriorate

MOT #8	2018-10-18 08:48
MOT test number	266646936440
Result	✓ Passed
Advice Slight smearing from front wipers [flat blades Advice Front and rear exhaust hangers weak	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT test number

Result

Advice Front and rear exhaust hangers weak

Pass with rectification Headlamp aim too high both (4.1.2 (a))

Advice Slight smearing from front wipers [flat blades

MOT #6

MOT test number

194633167804

Result

Advice Offside Rear Tyre worn close to the legal limit on 3mm 205/55r16 91v (4.1.E.1)

MOT test number

Result

Advice Offside rear Tyre has bad signs of cracking

Advice Direction indicator slightly discoloured both rear (1.4.A.2f)

 MOT #4
 2015-11-10 11:38

 MOT test number
 438317375984

 Result
 ✓ Passed

 MOT #3
 2015-11-09 13:38

 MOT test number
 683030236218

 Result
 X Failed

Front brake application uneven 33% imbalance (3.7.B.2)

Fail

CarCheck.co.uk page 5/13



AO10ZDH report date: 2024-03-29

MOT #2

MOT test number

756818394135

Result

MOT #1

2013-07-19 09:15

MOT test number

817590903266

Result

Notice Child seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	11 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK NIK
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



AO10ZDH report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



AO10ZDH report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-07-23
Last registration	2023-10-12
Complete history	See info



Registration #1	2010-07-23	13 mi
Registration #2	2013-07-19	29.317 mi
Registration #3	2014-07-17	34.867 mi
Registration #4	2015-11-09	44.280 mi
Registration #5	2015-11-10	44.291 mi
Registration #6	2016-10-10	51.547 mi
Registration #7	2017-10-23	62.956 mi
Registration #8	2018-10-18	71.066 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number AL38072