



Mercedes-Benz

**BSZ1027**

report date: 2024-03-28

General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Silver
Year of manufacture	2007
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	220 g/km
CO2 label	K






Internet history

Entry 2

Date	2024-03-27
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-08-04
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-06
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	32
Total items failed	6

MOT #17	2024-03-07 12:13
MOT test number	846066835714
Result	✓ Passed
Next expiry date	2025-03-06

MOT #16	2023-02-21 14:56
MOT test number	994415905468
Result	✓ Passed
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #15	2022-03-03 12:17
MOT test number	809352780411
Result	✓ Passed

MOT #14	2022-03-02 14:24
MOT test number	248399815203
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))



MOT #13

2020-11-04 10:52

MOT test number

504289420907

Result

✓ Passed

- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2020-11-02 16:58

**MOT test number**

289972540266

**Result****✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Fail** Anti-lock braking system warning lamp does not illuminate (1.6 (a))
- Advice** TPMS light on
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))

**MOT #11**

2019-10-24 09:06

**MOT test number**

740811171101

**Result****✓ Passed**

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front antiroll bar linkage gaiter perished

**MOT #10**

2018-11-03 12:53

**MOT test number**

589148280476

**Result****✓ Passed**

**MOT #9** 2018-10-31 12:52**MOT test number** 245680688416**Result** ✗ Failed**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Items removed from driver's view prior to test**MOT #8** 2017-11-09 13:59**MOT test number** 169123128199**Result** ✓ Passed**MOT #7** 2016-10-21 08:26**MOT test number** 607842036037**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2015-08-24 09:26**MOT test number** 543865132920**Result** ✓ Passed**MOT #5** 2014-08-28 10:41**MOT test number** 596550744281**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2013-08-28 10:34
MOT test number	916080643223
Result	✓ Passed
MOT #3	2012-08-29 10:59
MOT test number	117282342248
Result	✓ Passed
MOT #2	2011-08-12 10:00
MOT test number	297484421290
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
MOT #1	2010-08-04 09:47
MOT test number	390836310401
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 March 2024

✓

MOT

Expires:  
6 March 2025

Tax status	Expired at 1 March 2024
Days left	59 days too late
MOT expiry date	6 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 <b>BSZ1027</b>
Plate since	2024-03-28
Current registration	 <b>BSZ1027</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-01
Last registration	2024-03-07
Complete history	<a href="#">See info</a>



Registration #1	2007-09-01	18 mi
Registration #2	2010-08-04	15.019 mi
Registration #3	2011-08-12	20.104 mi
Registration #4	2012-08-29	25.532 mi
Registration #5	2013-08-28	29.368 mi
Registration #6	2014-08-28	34.350 mi
Registration #7	2015-08-24	39.286 mi
Registration #8	2016-10-21	42.985 mi
Registration #9	2017-11-09	54.855 mi
Registration #10	2018-10-31	68.648 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi
Registration #19	2019-05-29	75.277 mi
Registration #20	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040339215