



PK58ALO

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Grey
Year of manufacture	2008
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-09-23
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date	2021-09-21
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-09-19
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	44
Total items failed	16

MOT #17	2022-09-20 09:46
MOT test number	104712148750
Result	✓ Passed
Next expiry date	2023-09-19
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Hand brake lever has excessive travel
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #16**

2022-09-20 09:46

MOT test number

279476305232

Result**✗ Failed****Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Hand brake lever has excessive travel**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #15**

2021-09-20 15:14

MOT test number

130586782055

Result**✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear exhaust box slightly corroded**Advice** Parking brake needs slight adjustment**MOT #14**

2019-10-30 14:02

MOT test number

425516268531

Result**✓ Passed****Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #13**

2019-10-30 10:30

MOT test number

681733732073

Result

✗ Failed

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #12**

2018-11-01 11:04

MOT test number

185494527939

Result

✓ Passed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #11**

2018-10-30 11:49

MOT test number

610016890166

Result

✗ Failed

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))



MOT #10	2017-10-31 12:54
----------------	------------------

MOT test number	161895928762
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2017-10-31 09:03
---------------	------------------

MOT test number	766094534857
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8	2015-11-13 16:41
---------------	------------------

MOT test number	295683174014
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #7	2015-09-26 08:35
MOT test number	691188679403
Result	✓ Passed
Advice	Offside Front Direction indicator slightly discoloured (1.4.A.2f)
Advice	Offside Front Brake pad(s) wearing thin Pads around 75 to 85% worn. (3.5.1g)
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Recommend rear brake inspection of drum brakes, clean and adjust.
Advice	Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Wishbone rear pivot bush split and perishing. (2.4.G.2)
Advice	Parking brake lever has little reserve travel (3.1.6b)
Advice	Nearside Front Brake pad(s) wearing thin Pads around 75 to 85% worn. (3.5.1g)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Wishbone rear pivot bush split and perishing. (2.4.G.2)



MOT #6

2015-09-26 08:35

MOT test number

688472727713

Result

✗ Failed

Pass with rectification Offside Headlamp aim too low (1.8)**Advice** Nearside Front Brake pad(s) wearing thin Pads around 75 to 85% worn. (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Wishbone rear pivot bush split and perishing. (2.4.G.2)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Brake pad(s) wearing thin Pads around 75 to 85% worn. (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement Wishbone rear pivot bush split and perishing. (2.4.G.2)**Advice** Recommend rear brake inspection of drum brakes, clean and adjust.**Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #5

2014-10-08 09:24

MOT test number

209311284217

Result

✓ Passed

Notice N/S/F Tyre has a large cut but does not expose threads or cords

MOT #4

2013-10-07 17:24

MOT test number

985860983239

Result

✓ Passed



MOT #3	2013-10-07 16:33
MOT test number	415300583274
Result	✗ Failed
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #2	2012-10-10 08:04
MOT test number	577954582255
Result	✓ Passed

MOT #1	2011-10-11 16:52
MOT test number	597734481240
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 PK58ALO
Plate since	2024-03-28
Current registration	 PK58ALO
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-29
Last registration	2022-09-20
Complete history	See info



Registration #1	2008-09-29	21 mi
Registration #2	2011-10-11	31.181 mi
Registration #3	2012-10-10	34.002 mi
Registration #4	2013-10-07	36.425 mi
Registration #5	2013-10-07	36.425 mi
Registration #6	2014-10-08	41.972 mi
Registration #7	2015-09-26	46.888 mi
Registration #8	2015-09-26	46.888 mi
Registration #9	2015-11-13	47.483 mi
Registration #10	2017-10-31	62.633 mi
Registration #11	2019-05-20	75.377 mi
Registration #12	2019-05-20	75.377 mi
Registration #13	2019-05-20	75.377 mi
Registration #14	2019-05-20	75.377 mi
Registration #15	2019-05-20	75.377 mi
Registration #16	2019-05-20	75.377 mi
Registration #17	2019-05-20	75.377 mi
Registration #18	2019-05-20	75.377 mi
Registration #19	2019-05-20	75.377 mi
Registration #20	2019-05-20	75.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BMD 378141