






report date: 2024-03-29

#### General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	White
Year of manufacture	2015
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

### Engine & fuel consumption

Power	91 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history


#### Entry 1

Date 2021-07-18

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

Fail

MOT expiry date	2024-10-20
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	9
Total items failed	12

MOT #10		2023-10-07 12:22
MOT test	number	198241051407
Result		<b>✓</b> Passed
Next expiry date 2024-10-20		2024-10-20
Advice	Nearside Front Inner Brake disc worn, pitted or scored, but not seriously	weakened (1.1.14 (a) (ii))
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously w	eakened (1.1.14 (a) (ii))

MOT #9	2022-10-21 14:41
MOT test number	241354965780
Result	<b>√</b> Passed
MOT #8	2022-10-21 11:22

MOT #8 2022-10-21 11:22 MOT test number 932403310838

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #7	20	021-10-07 14:52
MOT test	number	362940493299
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

**MOT** #6 2021-10-07 10:04 383273013637 **MOT** test number Result × Failed Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Nearside Rear Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii)) Fail Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail

MOT #5	5	2021-10-02 10:00
MOT te	st number	540362558945
Result		<b>×</b> Failed
Fail	Nearside Rear Direction indicator incorrect colour (4.4.3 (a))	
Fail	Offside Front Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))	
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Nearside Front Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))	

Nearside Front Stop lamp(s) emits other than a steady red light (4.5.5 (a) (ii))		
MOT #4	2020-09-19 11:12	
MOT test number	910532072753	
Result	✓ Passed	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened The front discs are worn and corroded on the inner face. (1.1.14 (a) (ii))		
Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))		

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #3 2020-09-19 11:12

MOT test number 883516782679

**Result** X Failed

Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened The front discs are worn and corroded on the inner face. (1.1.14 (a) (ii))

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #2** 2019-10-05 10:42

**MOT test number** 343397494347

**Result** ✓ Passed

**MOT #1** 2018-10-06 09:45

**MOT test number** 553591977289

CarCheck.co.uk page 5/12



report date: 2024-03-29

See MOT history

#### Tax & MOT check

**Full MOT history** 



CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

Owner history	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
*********	
***************************************	
*************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIN
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-10-19
Last registration	2023-10-07
Complete history	See info



Registration #1	2015-10-19	20 mi
Registration #2	2018-10-06	21.047 mi
Registration #3	2019-10-05	26.161 mi
Registration #4	2020-09-19	28.708 mi
Registration #5	2020-09-19	28.708 mi
Registration #6		11.177 es
Registration #7		11.777 es
Registration #8		11.177 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		11.177 ms
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

## Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



## Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1965 kg

# Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles Carcheck.co.uk	2 page 12/1

**Engine number** 

C010924