



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D DRIVE SE LUX
Colour	Black
Year of manufacture	2010
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-11-07
Pictures	18
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-11-26
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	17
Total items failed	0

MOT #12	2023-11-27 09:38
MOT test number	384833034156
Result	✓ Passed
Next expiry date	2024-11-26
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11	2022-11-09 15:17
MOT test number	463181429901
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear arm bush (5.3.4 (a) (i))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear arm bush (5.3.4 (a) (i))

MOT #10	2021-10-14 14:34
MOT test number	850689511423
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	All 4 tyres wearing on edges
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9** 2021-10-14 14:00**MOT test number** 837651581279**Result** ✗ Failed**Advice** All 4 tyres wearing on edges**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MAJOR** Offside Front Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))**MOT #8** 2020-11-04 10:48**MOT test number** 753015882221**Result** ✓ Passed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2019-11-01 14:46**MOT test number** 572834080513**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge. (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge badly worn on inner edge. (5.2.3 (e))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2018-09-11 14:51**MOT test number** 644448506072**Result** ✓ Passed**MOT #5** 2017-08-26 11:01**MOT test number** 586067106311**Result** ✓ Passed



<b>MOT #4</b>	2016-09-12 09:27
<b>MOT test number</b>	742074946359
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)
<b>MOT #3</b>	2015-09-11 09:09
<b>MOT test number</b>	582888479153
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2014-09-12 10:37
<b>MOT test number</b>	475085554230
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
<b>MOT #1</b>	2013-11-28 13:35
<b>MOT test number</b>	486092433434
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
26 November 2024

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	26 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-29
Last registration	2023-11-27
Complete history	<a href="#">See info</a>



Registration #1	2010-12-29	27 mi
Registration #2	2013-11-28	119.529 mi
Registration #3	2014-09-12	145.182 mi
Registration #4	2015-09-11	159.516 mi
Registration #5	2016-09-12	167.171 mi
Registration #6	2017-08-26	176.655 mi
Registration #7	2018-09-11	195.535 mi
Registration #8	2019-09-27	211.277 mi
Registration #9	2020-09-27	221.277 mi
Registration #10	2021-09-27	231.277 mi
Registration #11	2022-09-27	241.277 mi
Registration #12	2023-09-27	251.277 mi
Registration #13	2024-03-28	261.277 mi
Registration #14	2024-03-28	271.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1676 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1343972