





report date: 2024-03-28

General information

Make	VOLVO
Model	V40 D4 BUSINESS EDITION
Colour	Grey
Year of manufacture	2015
Top speed	140 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2024-05-04
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	13
Total items failed	5

MOT #10		2023-05-05 10:17
MOT test	number	803889876681
Result		✓ Passed
Next expi	ry date	2024-05-04
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Advice Plastic cover sills, under floor covers and engine undertrays are fitted preventing inspection of	
componen	ts	
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #9		2023-05-04 11:02
MOT test	number	794630760183
Result		X Failed
	earside Front Tyre has a cut in excess of the requirements deep enough to wall (5.2.3 (d) (i))	reach the ply or cords
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Wearing on Inne	er Edge (5.2.3 (e))
Advice componen	Plastic cover sills, under floor covers and engine undertrays are fitted prests	venting inspection of
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 2/11



MOT #8 2022-03-23 14:26

MOT test number 838482279814

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2022-03-23 12:30

MOT test number 168579222703

Result X Failed

Advice TPMS light present

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #6 2021-04-01 15:21

MOT test number 466607428159

Result \sqrt{Passed}

MOT #5 2020-03-02 16:23

MOT test number 450789593884

Result \(\sqrt{Passed} \)

MOT #4 2020-03-02 11:35

MOT test number 634066676332

Result ★ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Offside Front Inner Tyre tread depth below requirements of 1.6mm edge (5.2.3 (e))

MOT #3 2019-03-01 09:48

MOT test number 803574281060

Result

Passed

CarCheck.co.uk page 3/11



KU15WKR

report date: 2024-03-28

MOT #2 2018-02-13 15:23 **MOT test number** 659707395135 ✓ Passed Result MOT #1 2018-02-13 12:20 245941616044 **MOT test number X** Failed Result **Advice** Nearside Rear cracking and cuts in tread Nearside Rear Tyre has ply or cords exposed (4.1.D.1b) Fail

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	4 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

*		
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.)

	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-04
Last registration	2023-05-05
Complete history	See info



Registration #1	2015-03-04	19 mi
Registration #2	2018-02-13	22.587 mi
Registration #3	2018-02-13	22.587 mi
Registration #4	2019-03-01	28.739 mi
Registration #5	2020-03-02	39.339 mi
Registration #6	2020-03-02	39.339 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		10.317 au

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1606 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/3

Number of axles2Engine number1159399