




report date: 2024-03-29

## General information

Make	FIAT
Model	DOBLO 8V ACTIVE
Colour	Grey
Year of manufacture	2006
Top speed	90 mph
0 - 60 mph	17.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.2 mpg
CO2 emission	174 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2025-04-04
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	28
Total items failed	26

MOT #24	2024-04-04 09:57
MOT test number	763391607170
Result	✓ Passed
Next expiry date	2025-04-04
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #23	2023-04-05 14:00
MOT test number	387352501725
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

MOT #22	2022-03-30 14:48
MOT test number	936677301567
Result	✓ Passed

MOT #21	2021-03-29 13:53
MOT test number	259254222816
Result	✓ Passed

**MOT #20**

2021-03-27 14:24

**MOT test number**

609838381871

**Result****✗ Failed****Fail**

Exhaust emissions carbon monoxide content excessive (8.2.1.2 (b))

**MOT #19**

2021-03-27 08:44

**MOT test number**

530527824196

**Result****✗ Failed****Advice**

Emissions test failed

**Minor**

Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice**

Suspension arm pin or bush worn but not resulting in excessive movement Rear bump stops deteriorating (5.3.4 (a) (i))

**Advice**

Surface rust under car

**Fail**

Exhaust has a major leak of exhaust gases (6.1.2 (a))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18**

2021-03-23 16:22

**MOT test number**

601052020835

**Result****✗ Failed****Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Advice** Surface rust under car**Advice** Registration plate deteriorated but not likely to be misread Both front and rear number plates slightly damaged. (0.1 (b))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Rear bump stops deteriorating (5.3.4 (a) (i))**Fail** Offside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure Tyre inner wall cracked and in bad condition (5.2.3 (d) (ii))**Fail** Fuel cap/sealing device ineffective Fuel cap not closing (6.1.3 (b) (i))**Advice** Emissions test failed**MOT #17**

2021-02-15 17:26

**MOT test number**

595195038395

**Result****✗ Failed****Fail** Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Dipswitch operation does not deflect all main beam headlamps to make them dipped beams (4.1.3 (b))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Fail** Parking brake lever pivot worn to the extent that the brake may inadvertently release (1.1.6 (b) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #16** 2020-03-24 13:06**MOT test number** 400808275323**Result** ✓ Passed**MOT #15** 2019-03-19 16:51**MOT test number** 918525128034**Result** ✓ Passed**MOT #14** 2018-03-15 17:19**MOT test number** 585156596295**Result** ✓ Passed**MOT #13** 2018-03-15 17:19**MOT test number** 647745840313**Result** ✗ Failed**Pass with rectification** Exhaust has a major leak of exhaust gases (7.1.2)**MOT #12** 2017-03-10 17:09**MOT test number** 780861171412**Result** ✓ Passed**MOT #11** 2016-03-12 12:33**MOT test number** 220012703836**Result** ✓ Passed**Advice** Exhaust system corroded and weakened**Advice** Engine oil sump corroded & leaking**MOT #10** 2015-03-14 11:25**MOT test number** 317173675097**Result** ✓ Passed



<b>MOT #9</b>	2014-03-14 10:17
<b>MOT test number</b>	538313174030
<b>Result</b>	✓ Passed
<b>Notice</b>	N/s/f lower suspension arm - bushes worn/split

<b>MOT #8</b>	2013-03-26 15:45
<b>MOT test number</b>	918075283027
<b>Result</b>	✓ Passed
<b>Notice</b>	Exhaust flexi-section split (but not leaking)

<b>MOT #7</b>	2013-03-26 11:00
<b>MOT test number</b>	615915383012
<b>Result</b>	✗ Failed
<b>Notice</b>	Both front brake discs worn/corroded
<b>Fail</b>	Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
<b>Notice</b>	Exhaust flexi-section split (but not leaking)
<b>Fail</b>	Brakes imbalanced across an axle (3.7.B.5b)
<b>Fail</b>	Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
<b>Notice</b>	Front brake pad set wearing unevenly and low
<b>Fail</b>	Front brake application uneven (3.7.B.2)

<b>MOT #6</b>	2012-03-27 16:31
<b>MOT test number</b>	456817482067
<b>Result</b>	✓ Passed
<b>Notice</b>	Unable to carry out full examination of rear seat belts as dog protection fitted to seats
<b>Notice</b>	Slight scoring to o/s lower windscreen

**MOT #5** 2012-03-27 13:04**MOT test number** 509247782028**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too far to the right (1.8)**Notice** Unable to carry out full examination of rear seat belts as dog protection fitted to seats**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Pass with rectification** Offside Headlamp aim too far to the right (1.8)**Notice** Slight scoring to o/s lower windscreen**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-04-04 16:45**MOT test number** 205294291093**Result** ✓ Passed**Notice** Light score on windscreen, not impairing driver's view**MOT #3** 2011-04-01 11:01**MOT test number** 995061191054**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has an excessively worn bush (2.7.4)**Fail** Nearside Front Windscreen wiper not operating automatically when switched on (8.2.1b)**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Notice** Light score on windscreen, not impairing driver's view



MOT #2	2010-02-15 12:11
MOT test number	360436340005
Result	✓ Passed

MOT #1	2009-07-17 12:06
MOT test number	110358699141
Result	✓ Passed

**Advice** Offside Rear reflector obscured but not more than 50% (1.5.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
4 April 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	4 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>PN56PYX</b>
Plate since	2024-03-29
Current registration	<b>PN56PYX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2006-09-29
Last registration	2024-04-04
Complete history	<a href="#">See info</a>



Registration #1	2006-09-29	21 mi
Registration #2	2009-07-17	17.440 mi
Registration #3	2010-02-15	19.789 mi
Registration #4	2011-04-01	27.982 mi
Registration #5	2011-04-04	27.982 mi
Registration #6	2012-03-27	34.833 mi
Registration #7	2012-03-27	34.833 mi
Registration #8	2013-03-26	41.953 mi
Registration #9	2013-03-26	41.954 mi
Registration #10	2014-03-14	48.190 mi
Registration #11	2015-03-14	54.831 mi
Registration #12	2016-03-12	61.501 mi
Registration #13	2017-03-10	67.798 mi
Registration #14	2018-03-10	74.098 mi
Registration #15	2019-03-10	80.398 mi
Registration #16	2020-03-10	86.698 mi
Registration #17	2021-03-10	92.998 mi
Registration #18	2022-03-10	99.298 mi
Registration #19	2023-03-10	105.598 mi
Registration #20	2024-03-10	111.898 mi
Registration #21	2025-03-10	118.198 mi
Registration #22	2026-03-10	124.498 mi
Registration #23	2027-03-10	130.798 mi
Registration #24	2028-03-10	137.098 mi
Registration #25	2029-03-10	143.398 mi
Registration #26	2030-03-10	149.698 mi

**More info** >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1722 mm
Height	2073 mm
Length	4253 mm
Wheel base	2583 mm
Kerb weight	1230 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	3423887