



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	JETTA SPORT TDI
Colour	Black
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	160 g/km
CO2 label	G







Internet history

Entry 1

Date	2021-08-10
Pictures	28
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-19
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	41
Total items failed	5

MOT #15	2023-06-20 14:33
MOT test number	413063509650
Result	✓ Passed
Next expiry date	2024-06-19
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14** 2023-06-20 10:59**MOT test number** 339537574211**Result** ✗ Failed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #13** 2021-08-18 10:44**MOT test number** 687150935909**Result** ✓ Passed**MOT #12** 2021-08-18 10:44**MOT test number** 341434100776**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Pass with rectification** Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))

**MOT #11**

2020-09-30 10:24

MOT test number

590165509071

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm bushes worn (5.3.4 (a) (i))**Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))**MOT #10**

2019-05-10 09:57

MOT test number

110754851237

Result

✓ Passed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #9**

2018-05-21 15:58

MOT test number

102000106352

Result

✓ Passed

MOT #8

2017-06-28 14:33

MOT test number

724125001345

Result

✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Under covers fitted**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Items removed from driver's view prior to test

**MOT #7** 2016-06-29 11:27**MOT test number** 783419144618**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Nail in tyre**Advice** Under covers fitted**MOT #6** 2015-06-08 17:18**MOT test number** 219319155446**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2014-05-21 11:57**MOT test number** 196941344113**Result** ✓ Passed**Notice** Offside rear tyre is deteriorating cracks in tread.**MOT #4** 2013-05-28 09:09**MOT test number** 256548543136**Result** ✓ Passed**MOT #3** 2012-05-15 12:31**MOT test number** 868236432152**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #2** 2011-05-24 14:12**MOT test number** 535634641164**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Notice** No smoke emitted = no emissions printout = pass**MOT #1** 2011-05-24 14:12**MOT test number** 617914341187**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Notice** No smoke emitted = no emissions printout = pass**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 June 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	19 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-06-01
Last registration	2023-06-20
Complete history	See info



Registration #1	2008-06-01	8 mi
Registration #2	2011-05-24	21.755 mi
Registration #3	2012-05-15	29.276 mi
Registration #4	2013-05-28	36.419 mi
Registration #5	2014-05-21	43.136 mi
Registration #6	2015-06-08	48.136 mi
Registration #7	2016-06-29	59.620 mi
Registration #8	2017-06-28	61.438 mi
Registration #9	2018-06-20	61.438 mi
Registration #10	2019-06-20	61.438 mi
Registration #11	2020-06-20	61.438 mi
Registration #12	2021-06-20	61.438 mi
Registration #13	2022-06-20	61.438 mi
Registration #14	2023-06-20	61.438 mi
Registration #15	2024-06-20	61.438 mi
Registration #16	2025-06-20	61.438 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1568 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BKD 519015