





report date: 2024-03-29

## General information

Make	CITROEN
Model	DS4 HDI DSTYLE
Colour	Blue
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	115 BHP	
Max. torque	270 Nm at 1.750 rpm	
Engine capacity	1.560 cc	
Cylinders	4	
Fuel type	Diesel	
Consumption city	47.9 mpg	
Consumption extra urban	70.6 mpg	
Consumption combined	60.1 mpg	
CO2 emission	122 g/km	
CO2 label	D	



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-29

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



MT61FBK report date: 2024-03-29

MOT history

MOT expiry date	2024-11-26
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	16
Total items failed	11

MOT #13	2023-11-27 11:38
MOT test number	714891789530
Result	✓ Passed
Next expiry date	2024-11-26
Minor Offside Front Drive shaft joint constant velocity boot severely dete	eriorated (6.1.7 (g) (i))

MOT #12	2023-01-09 13:19
MOT test number	496860736032
Result	<b>✓</b> Passed

MOT #11	2022-12-30 16:24
MOT test number	810170249268
Result	<b>X</b> Failed
Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (i	i))
Fail Front Service brake excessively fluctuating both (1.2.3)	1 (e))
Advice Nearside Rear Tyre worn close to legal limit/worn c(e))	on edge wearing uneven on inner edge (5.2.3
Fail Nearside Front Suspension arm ball joint dust cover no (ii))	o longer prevents the ingress of dirt (5.3.4 (b)
Fail Front Brake disc significantly and obviously worn both	(1.1.14 (a) (i))
Advice Offside Rear Tyre worn close to legal limit/worn on visible cord shown (5.2.3 (e))	edge close to limit and various cuts but no
Fail Registration plate lamp inoperative in the case of a sir	ngle lamp or all lamps both (4.7.1 (b) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-29

**MOT #10** 2021-10-12 10:41

MOT test number 451397661088

**Result** ✓ Passed

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #9 2020-10-05 09:44

**MOT test number** 169697403364

**Result** ✓ Passed

MOT #8 2019-10-14 14:48

**MOT test number** 937908983392

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2019-10-09 09:58

MOT test number 613214728048

**Result** X Failed

**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both not working (4.7.1 (b) (ii))

**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2018-09-11 07:25

**MOT test number** 953900135782

Result 

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #5 2017-11-24 10:05

**MOT test number** 158697931812

Result \rightarrow Passed

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2016-11-25 15:08

MOT test number 656924591443

**Result** ✓ Passed

**Advice** Lip of corrosion on inner face of both front brake discs

**Advice** Nearside wiper leaving smears

MOT #3 2016-11-25 11:07

MOT test number 221765575451

**Result** X Failed

**Advice** Nearside wiper leaving smears

**Fail** Nearside Headlamp aim too high (1.8)

**Advice** Both rear tyres have large cracks forming on inner and outer tread edges

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Headlamp aim too high (1.8)

**Advice** Lip of corrosion on inner face of both front brake discs

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2015-11-13 09:39

**MOT test number** 907276406986

**Result** 
✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1 2014-12-12 15:26

**MOT test number** 916256644380

CarCheck.co.uk page 6/13



report date: 2024-03-29

## Tax & MOT check



✓ MOT

Tax status	Valid until 1 February
Days left	278
MOT expiry date	26 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
THE STATE OF THE S	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Mumber of prates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-12-08
Last registration	2023-11-27
Complete history	See info



Registration #1	2011-12-08	19 mi
Registration #2	2014-12-12	38.929 mi
Registration #3	2015-11-13	44.731 mi
Registration #4	2016-11-25	50.925 mi
Registration #5	2016-11-25	50.925 mi
Registration #6	2017-11-24	56.860 mi
Registration #7	2018-09-11	61.865 mi
Registration #8	2019-10-09	78.305 mi
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 12/13



MT61FBK report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1523 mm
Length	4275 mm
Wheel base	2612 mm
Kerb weight	1320 kg
Max. allowed weight	1805 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBET3005152

CarCheck.co.uk page 13/13