



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM SE
Colour	White
Year of manufacture	2015
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	41.5 mpg
CO2 emission	178 g/km
CO2 label	I






Internet history

Entry 1

Date	2021-07-04
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	21
Total items failed	1

MOT #8	2024-01-16 15:41
MOT test number	430060792599
Result	✓ Passed
Next expiry date	2025-01-15
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #7	2024-01-16 15:41
MOT test number	522178985584
Result	✗ Failed
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Nearside Front Lower Sub-frame ball joint likely to become detached (5.3.4 (a) (ii))
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #6** 2023-01-16 12:00**MOT test number** 858321262351**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2023-01-14 16:03**MOT test number** 676698452665**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2022-01-14 16:56**MOT test number** 641078332000**Result** ✓ Passed**Advice** Nearside Front wiper blade split**Advice** Tyre pressure light on



MOT #3	2020-12-23 13:44
MOT test number	800095834742
Result	✓ Passed

MOT #2	2019-12-28 12:46
MOT test number	252545005222
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

MOT #1	2018-12-20 17:05
MOT test number	892858842370
Result	✓ Passed
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
15 January 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	15 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	KV15DYG
Plate since	2015-03-28
Current registration	KV15DYG
Plate since	2015-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-31
Last registration	2024-01-16
Complete history	See info



Registration #1	2015-03-31	27 mi
Registration #2	2018-12-20	56.597 mi
Registration #3	2019-12-28	68.517 mi
Registration #4	2020-12-23	77.139 mi
Registration #5	2020-05-20	75.277 mi
Registration #6	2019-05-20	75.277 mi
Registration #7	2019-05-20	75.277 mi
Registration #8	2019-05-20	75.277 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	89%
Pedestrian	71%
Safety systems	86%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	1880 mm
Height	1690 mm
Length	4690 mm
Wheel base	2700 mm
Kerb weight	2001 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBFU166682