



report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT GLX
Colour	Turquoise
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	133 Nm at 4.100 rpm
Engine capacity	1.490 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	45.6 mpg
CO2 emission	145 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-06-13
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-18
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	42
Total items failed	5

MOT #19	2024-02-19 13:34
MOT test number	813217530826
Result	✓ Passed
Next expiry date	2025-02-18

MOT #18	2023-02-07 16:17
MOT test number	991823299961
Result	✓ Passed
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Rear fuel lines corroded

MOT #17	2023-02-07 15:33
MOT test number	837687758506
Result	✗ Failed
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))
MAJOR	Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
Advice	Nearside Rear fuel lines corroded

**MOT #16**

2023-01-24 10:53

MOT test number

591959548928

Result**✗ Failed****Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**DANGEROUS** Nearside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))**MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively split (3.4 (b) (ii))**MAJOR** Offside Front Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #15**

2022-01-17 11:04

MOT test number

975315601717

Result**✓ Passed****Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened ns and os (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #14**

2021-01-25 15:46

MOT test number

111887642338

Result**✓ Passed****Advice** Surface corrosion to front and rear suspension components inc coil springs

**MOT #13**

2021-01-22 12:09

MOT test number

524639229600

Result**✗ Failed****Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords outer wall (5.2.3 (d) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR

Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR

Offside Front Suspension arm pin or bush excessively worn wishbone (5.3.4 (a) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Surface corrosion to front and rear suspension components inc coil springs

MAJOR

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

MAJOR

Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #12

2019-10-04 11:37

MOT test number

756182052978

Result**✓ Passed****Advice**

Coil spring corroded both front (5.3.1 (b) (i))

MOT #11

2019-10-04 09:34

MOT test number

390233931205

Result**✗ Failed****Advice**

Offside Rear Service brake binding but not excessively (1.2.1 (f))

MAJOR

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice

Coil spring corroded both front (5.3.1 (b) (i))

**MOT #10** 2018-09-22 11:16**MOT test number** 239484001867**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #9** 2018-09-22 11:16**MOT test number** 248027457331**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**MOT #8** 2017-10-02 12:24**MOT test number** 319950161108**Result** ✓ Passed**MOT #7** 2017-10-02 11:22**MOT test number** 324380786740**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**MOT #6** 2016-11-08 15:11**MOT test number** 433973106172**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-11-08 12:53**MOT test number** 375200986095**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Front Suspension arm has excessive play in a ball joint and o/s/f (2.4.G.2)**MOT #4** 2015-11-05 11:58**MOT test number** 970305807450**Result** ✓ Passed**MOT #3** 2014-12-15 15:14**MOT test number** 328819744312**Result** ✓ Passed**MOT #2** 2013-09-03 10:42**MOT test number** 269886443233**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-09-24 08:59**MOT test number** 395668862447**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 February 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	18 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-05
Last registration	2024-02-19
Complete history	See info



Registration #1	2009-09-05	7 mi
Registration #2	2012-09-24	34.945 mi
Registration #3	2013-09-03	46.396 mi
Registration #4	2014-12-15	60.713 mi
Registration #5	2015-11-05	68.136 mi
Registration #6	2016-11-08	76.482 mi
Registration #7	2016-11-08	76.482 mi
Registration #8	2017-10-02	83.339 mi
Registration #9	2017-10-02	83.339 mi
Registration #10	2018-09-22	89.861 mi
Registration #11	2018-09-22	89.861 mi
Registration #12	2019-09-22	96.383 mi
Registration #13	2019-09-22	96.383 mi
Registration #14	2020-09-22	102.905 mi
Registration #15	2020-09-22	102.905 mi
Registration #16	2021-09-22	109.427 mi
Registration #17	2021-09-22	109.427 mi
Registration #18	2022-09-22	115.949 mi
Registration #19	2022-09-22	115.949 mi
Registration #20	2023-09-22	122.471 mi
Registration #21	2024-02-19	128.993 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1690 mm
Height	1500 mm
Length	3835 mm
Wheel base	2380 mm
Kerb weight	1075 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M15A-1368814