



EF60A0H

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT T230 HR P/V
Colour	Blue
Year of manufacture	2011
Top speed	10 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	1.0 mpg
Consumption extra urban	1.0 mpg
Consumption combined	1.0 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-01
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	30
Total items failed	16

MOT #16	2023-10-23 07:27
---------	------------------

MOT test number	386395400006
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-22
------------------	------------

- Advice

Play in steering rack inner joint(s) Both
- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor

Offside Front Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))
- Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #15**

2023-10-17 08:31

**MOT test number**

451637184056

**Result****✗ Failed****Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))**Advice** Play in steering rack inner joint(s) Both**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (within 30cm) (5.3.6 (a) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Minor** Windscreen wiper blade defective smearing the screen (3.4 (b) (i))**Fail** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #14**

2022-10-18 13:28

**MOT test number**

436953558488

**Result****✓ Passed****Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Front Play in steering rack inner joint(s)

**MOT #13** 2022-10-15 12:46**MOT test number** 126258574275**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front Play in steering rack inner joint(s)**Fail** Nearside Rear Brake pipe excessively corroded brake pipe n/s rear right to left (1.1.11 (c))**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Front Play in steering rack inner joint(s)**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #12** 2021-10-21 10:39**MOT test number** 429053099441**Result** ✓ Passed**MOT #11** 2021-10-20 14:37**MOT test number** 767579536650**Result** ✗ Failed**Fail** Offside Rear Other passenger door cannot be opened from outside the vehicle passenger door. (6.2.3 (a))**MOT #10** 2021-01-07 16:24**MOT test number** 124914708105**Result** ✓ Passed**MOT #9** 2020-01-15 11:04**MOT test number** 929602871431**Result** ✓ Passed

**MOT #8** 2019-01-16 14:18**MOT test number** 457625745029**Result** ✓ Passed**MOT #7** 2018-01-18 12:53**MOT test number** 372667921924**Result** ✓ Passed**Advice** Front fog light's glass is broken**Advice** Exhaust has a minor leak of exhaust gases centre pipe (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2017-01-27 09:15**MOT test number** 110767974064**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear Direction indicators slightly discoloured both bulbs (1.4.A.2f)**MOT #5** 2016-01-15 13:13**MOT test number** 787483185429**Result** ✓ Passed**MOT #4** 2016-01-15 09:02**MOT test number** 957352400267**Result** ✗ Failed**Fail** Fuel system component leaking vent pipe on top of tank leaking (7.2.3)**MOT #3** 2015-02-04 09:03**MOT test number** 325765135063**Result** ✓ Passed

**MOT #2**

2014-01-27 09:43

**MOT test number**

166977924490

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/f tyre bald on inner edge**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/f tyre bald on inner edge**MOT #1**

2014-01-27 09:43

**MOT test number**

517077224094

**Result**

✗ Failed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/f tyre bald on inner edge**Pass with rectification** Upper Stop lamp not working (1.2.1b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s/f tyre bald on inner edge



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
22 October 2024

Tax status		Valid until 1 November
Days left		186
MOT expiry date		22 October 2024
Full MOT history		<a href="#">See MOT history</a>





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>EF60AOH</b>
Plate since	2019-09-29
Current registration	<b>EF60AOH</b>
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-02-10
Last registration	2023-10-23
Complete history	<a href="#">See info</a>



Registration #1	2011-02-10	6 mi
Registration #2	2014-01-27	57.455 mi
Registration #3	2015-02-04	77.358 mi
Registration #4	2016-01-15	95.645 mi
Registration #5	2016-01-15	95.645 mi
Registration #6	2017-01-27	115.415 mi
Registration #7	2018-01-18	132.326 mi
Registration #8	2019-01-16	147.395 mi
Registration #9	2020-01-15	164.955 mi
Registration #10	2020-01-15	164.955 mi
Registration #11	2020-01-15	164.955 mi
Registration #12	2020-01-15	164.955 mi
Registration #13	2020-01-15	164.955 mi
Registration #14	2020-01-15	164.955 mi
Registration #15	2020-01-15	164.955 mi
Registration #16	2020-01-15	164.955 mi
Registration #17	2020-01-15	164.955 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	1980 mm
Length	4525 mm
Kerb weight	1438 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Number of axles	2
Engine number	AG11065