





report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO T-JET BLACK 2
Colour	Black
Year of manufacture	2014
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/13



DV64MTJ

report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-11

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-09
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	30
Total items failed	3

MOT #13	2023-11-08 11:36	
MOT test number	550031630694	
Result	✓ Passed	
Next expiry date	2024-11-09	
Advice Offside Rear Brake cable damaged but not to excess Outer casing. (1	L.1.15 (a))	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))		
Advice Front Both day time running lights not working.		
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))		
Advice Rear Exhaust box corroded.		
Advice Nearside Front brake pad sensor wire broken (no light on dash)		

CarCheck.co.uk page 3/13



Result

DV64MTJ

report date: 2024-03-29

× Failed

MOT #12 2023-11-06 15:41

MOT test number 528246624968

Advice Nearside Front brake pad sensor wire broken (no light on dash)

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Front Both day time running lights not working.

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MAJOR Windscreen washer not working (3.5 (a))

Advice Rear Exhaust box corroded.

Advice Offside Rear Brake cable damaged but not to excess Outer casing. (1.1.15 (a))

MOT #11 2022-11-10 10:38

MOT test number 481167947713

Result \(\sqrt{Passed} \)

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #10 2022-02-21 15:04

MOT test number 169691228462

Result
✓ Passed

Advice Rear Coil spring corroded both rears (5.3.1 (b) (i))

Advice Exhaust backbox outer skin deteriated

CarCheck.co.uk page 4/13



DV64MTJ

report date: 2024-03-29

MOT #9 2022-02-21 09:15

MOT test number 813883292934

Result X Failed

MAJOR Offside Rear Tyre not fitted in accordance with side wall instructions direction rotation (5.2.3 (i))

DANGEROUS Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Rear Coil spring corroded both rears (5.3.1 (b) (i))

Advice Exhaust backbox outer skin deteriated

MOT #8 2021-02-23 12:08

MOT test number 740712793558

Result ✓ Passed

MOT #7 2020-02-08 12:37

MOT test number 701807302314

Result

Passed

Advice Offside Rear Brake cable damaged but not to excess (1.1.15 (a))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened bothside worn (1.1.14 (a) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords inner wall (5.2.3 (d) (i))

MOT #6 2020-02-08 12:37

MOT test number 109070858592

Result × Failed

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Offside Rear Brake cable damaged but not to excess (1.1.15 (a))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords inner wall (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened bothside worn (1.1.14 (a) (ii))

CarCheck.co.uk page 5/13



DV64MTJ

report date: 2024-03-29

MOT #5 2019-02-08 16:38

MOT test number 384271505106

Result ✓ Passed

MOT #4 2019-02-08 09:07

MOT test number 619441283615

Result ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #3 2018-09-25 10:06

MOT test number 205544793579

Result Passed

Advice Coil spring corroded all on lower sections (5.3.1 (b) (i))

MOT #2 2017-09-08 16:16

MOT test number 316368755592

MOT #1 2017-09-06 13:51

MOT test number 795907638651

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	9 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-09-30
Last registration	2023-11-08
Complete history	See info



Registration #1	2014-09-30	13 mi
Registration #2	2017-09-06	22.225 mi
Registration #3	2017-09-08	22.242 mi
Registration #4	2018-09-25	35.942 mi
Registration #5	2019-02-08	41.657 mi
Registration #6	2019-02-08	41.657 mi
Registration #7	2020-02-08	46.042 mi
Registration #8	2020-02-08	46.042 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.177 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1025 kg
Max. allowed weight	1585 kg

Additional information

·	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2
Engine number 0760625