



General information

Make	FIAT
Model	PANDA MAMY
Colour	Black
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	102 Nm at 2.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	50.4 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-06-16
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	20
Total items failed	5

MOT #14	2023-05-31 08:49
MOT test number	835877516798
Result	✓ Passed
Next expiry date	2024-06-16

MOT #13	2022-05-24 10:00
MOT test number	416503362806
Result	✓ Passed
Advice	Rear Suspension arm corroded but not seriously weakened Swing arm (5.3.3 (b) (i))

MOT #12	2021-06-17 15:54
MOT test number	390858328187
Result	✓ Passed
Advice	Under vehicle suspension/braking/exhaust components are slightly corroded
Advice	Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11** 2021-06-12 13:50**MOT test number** 643109737549**Result** ✗ Failed**Fail** Front Suspension arm pin or bush excessively worn both sides wishbone bushes (5.3.4 (a) (i))**Fail** Rear Upper Shock absorbers has an excessively worn bush both sides (5.3.2 (c))**Advice** Under vehicle suspension/braking/exhaust components are slightly corroded**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2020-03-14 11:30**MOT test number** 970551849718**Result** ✓ Passed**MOT #9** 2019-06-24 11:45**MOT test number** 418831327058**Result** ✗ Failed**Fail** Offside Front Suspension arm pin or bush excessively worn rear bush bonding broken away from arm (5.3.4 (a) (i))**Advice** Rear exhaust box deteriorated**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush bonding broken away from arm (5.3.4 (a) (i))**Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Rear exhaust clamp missing**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2019-03-05 15:44**MOT test number** 932022690005**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**MOT #7** 2018-03-12 16:50**MOT test number** 338659792271**Result** ✓ Passed**MOT #6** 2017-03-18 09:01**MOT test number** 276119355089**Result** ✓ Passed**Advice** Front tyres worn inner edge**MOT #5** 2016-03-14 09:11**MOT test number** 309875939007**Result** ✓ Passed**MOT #4** 2015-03-28 10:11**MOT test number** 367537885002**Result** ✓ Passed**Notice** Corrosion/wear on rear exhaust**MOT #3** 2014-03-28 11:28**MOT test number** 165677684453**Result** ✓ Passed**Notice** Rear silencer corroded but not blowing



MOT #2	2013-03-30 09:49
MOT test number	569129683090
Result	✓ Passed
Notice	Corrosion/wear on rear exhaust

MOT #1	2012-03-24 11:42
MOT test number	685204982082
Result	✓ Passed
Advice	Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Notice	Part of the exhaust system has deteriorated



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
16 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	34
<b>MOT expiry date</b>	16 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-31
Last registration	2023-05-31
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	8 mi
Registration #2	2012-03-24	14.892 mi
Registration #3	2013-03-30	18.547 mi
Registration #4	2014-03-28	22.336 mi
Registration #5	2015-03-28	26.611 mi
Registration #6	2016-03-14	31.680 mi
Registration #7	2017-03-18	35.413 mi
Registration #8	2018-03-12	39.424 mi
Registration #9	2019-03-20	43.435 mi
Registration #10	2020-03-19	47.446 mi
Registration #11	2021-03-18	51.457 mi
Registration #12	2022-03-17	55.468 mi
Registration #13	2023-03-16	59.479 mi
Registration #14	2024-03-15	63.490 mi
Registration #15	2025-03-14	67.501 mi
Registration #16	2026-03-13	71.512 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	860 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	4653568