





report date: 2024-03-29

### General information

Make	TOYOTA
Model	VERSO VALVEMATIC TR
Colour	Silver
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

### Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2019-05-07
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	10
Total items failed	9

MOT #13	2018-05-08 11:09
MOT test number	861518638101
Result	<b>✓</b> Passed
Next expiry date	2019-05-07
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #12	2018-05-08 09:44	
MOT test number	855772978693	
Result	<b>X</b> Failed	
Pass with rectification	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)	
Fail Nearside Rear Tyre	has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)	
Pass with rectification	Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)	
Pass with rectification	Nearside Rear Registration plate lamp not working (1.1.C.1d)	
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)		
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		

MOT #11	2017-07-27 08:39
MOT test number	254611056512
Result	<b>✓</b> Passed

CarCheck.co.uk page 2/10



MOT #10 2017-01-16 12:30

**MOT test number** 137784074915

MOT #9 2016-07-04 09:56

**MOT test number** 510199091016

**Advice** Nearside Rear Nail in tyre

MOT #8 2016-01-06 11:48

**MOT test number** 274868631214

**Result** ✓ Passed

MOT #7 2015-07-15 13:11

**MOT test number** 687826395127

**Result** ✓ Passed

MOT #6 2015-01-12 17:59

**MOT test number** 468912215059

**Result** 
✓ Passed

**Advice** Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)

Notice Both rear lights deteriorating

**Notice** Nearside front tyre wearing on outer edge

CarCheck.co.uk page 3/10



MOT #5 2015-01-12 15:22

**MOT test number** 517642615001

**Result** X Failed

**Notice** Nearside front tyre wearing on outer edge

Fail Offside Front Headlamp insecure (1.7.3)

Advice Offside Front Headlamp deteriorated but light output not reduced (1.7.5a)

Fail Nearside Front Headlamp insecure (1.7.3)

**Notice** Both rear lights deteriorating

**Fail** Front registration plate deteriorated (6.3.1d)

MOT #4 2014-10-16 17:35

**MOT test number** 336939184251

**Result** ✓ Passed

**MOT #3** 2013-10-05 17:00

**MOT test number** 387248173285

Result 

Passed

**Notice** N/s/r tyre wear outer edges

MOT #2 2012-04-25 16:33

**MOT test number** 257956612447

**Result** ✓ Passed

MOT #1 2011-10-24 15:18

**MOT test number** 429477391215

**Result** ✓ Passed

CarCheck.co.uk page 4/10



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



EK10HZA

report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
********	
***************************************	
************	
********	
***************************************	
THE STREET	
	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NA
Plate since	
Current registration	UK NE
Plate since	
	More info

CarCheck.co.uk page 7/10



#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10




**EK10HZA** 

report date: 2024-03-29

## Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-03-25
Last registration	2018-05-08
Complete history	See info



Registration #1	2010-03-25	25 mi
Registration #2	2011-10-24	3.965 mi
Registration #3	2012-04-25	17.925 mi
Registration #4	2013-10-05	34.710 mi
Registration #5	2014-10-16	43.846 mi
Registration #6	2015-01-12	44.238 mi
Registration #7	2015-01-12	44.239 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		0.00 44
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 9/10



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



## Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg

# Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 10/10