



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI DSG
Colour	Silver
Year of manufacture	2013
Top speed	114 mph
0 - 100 km/h	12.8 seconds
0 - 60 mph	12.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 103 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2022-02-12
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	31
Total items failed	6

MOT #11	2024-03-14 09:23
MOT test number	642746216602
Result	✓ Passed
Next expiry date	2025-03-24

MOT #10	2023-03-08 11:34
MOT test number	802001411186
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2022-03-25 14:58
MOT test number	219975742727
Result	✓ Passed

**MOT #8**

2021-10-15 07:37

MOT test number

946618100209

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #7

2021-10-13 12:46

MOT test number

737479551480

Result

✗ Failed

- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Nail in tyre
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Electronic power steering warning lamp indicates a system malfunction (2.6 (a))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #6

2020-10-01 16:17

MOT test number

301751297410

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #5** 2020-10-01 10:18**MOT test number** 982091029255**Result** ✗ Failed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brake pad(s) wearing thin ON LIMIT (1.1.13 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #4 2019-04-15 08:41**MOT test number** 665417442559**Result** ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #3 2018-04-17 07:26**MOT test number** 532594196608**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2017-04-21 09:59**MOT test number** 637717825749**Result** ✓ Passed**Advice** Nearside Rear Tyre bald on edge but no cords exposed at time of test.**Advice** Offside Front Tyre worn on edge.**Advice** Nearside Front Tyre worn on edge.**Advice** Undertrays fitted.**Advice** Offside Front Tyre perished.**Advice** Nearside Front Tyre perished.**MOT #1** 2016-03-14 12:59**MOT test number** 200918648868**Result** ✓ Passed**Advice** Nearside Rear tyre is feathered on inner edge**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement n/s & o/s front wishbone bushes (2.4.G.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** N/s & o/s front inner edges**Advice** Tyre worn close to the legal limit n/s & o/s front inner edges (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	BX13TKT
Plate since	2019-03-29
Current registration	BX13TKT
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-22
Last registration	2024-03-14
Complete history	See info



Registration #1	2013-03-22	8 mi
Registration #2	2016-03-14	62.267 mi
Registration #3	2017-04-21	67.374 mi
Registration #4	2018-04-17	73.180 mi
Registration #5	2019-04-15	80.509 mi
Registration #6	2020-10-01	88.376 mi
Registration #7	2020-10-01	88.376 mi
Registration #8	2020-10-01	88.376 mi
Registration #9	2020-10-01	88.376 mi
Registration #10	2020-10-01	88.376 mi
Registration #11	2020-10-01	88.376 mi
Registration #12	2020-10-01	88.376 mi
Registration #13	2020-10-01	88.376 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1674 mm
Length	4397 mm
Wheel base	2678 mm
Kerb weight	1485 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of axles	2
Engine number	CAYCT89308