



PEUGEOT



KR07UAJ


report date: 2024-03-29

General information

Make	PEUGEOT
Model	1007 DOLCE
Colour	Silver
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-11-03
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-03
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	45
Total items failed	14

MOT #23 2023-10-25 14:17

MOT test number 537409557083

Result ✓ Passed

Next expiry date 2024-11-03

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front wishbone bush (5.3.4 (a) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #22 2022-10-26 13:41

MOT test number 116395706891

Result ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #21** 2021-11-04 14:24**MOT test number** 620296028731**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear Exhaust Box Corroded**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #20** 2021-11-04 13:27**MOT test number** 920452911720**Result** ✗ Failed**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust Box Corroded**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MAJOR** Rear Exhaust system insecure (6.1.2 (a))**MOT #19** 2021-01-14 09:28**MOT test number** 258798950430**Result** ✓ Passed

**MOT #18** 2021-01-14 09:28**MOT test number** 613449260702**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #17** 2019-07-11 08:45**MOT test number** 737949184901**Result** ✓ Passed**MOT #16** 2018-07-05 08:06**MOT test number** 333036828989**Result** ✓ Passed**MOT #15** 2018-07-04 10:17**MOT test number** 908792902626**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**MOT #14** 2017-07-20 09:35**MOT test number** 465952009839**Result** ✓ Passed**Advice** Headlamp has a product on the lens but not seriously reducing light output both (1.7.5a)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #13** 2016-07-11 14:04**MOT test number** 802573072774**Result** ✓ Passed**MOT #12** 2016-07-11 10:33**MOT test number** 612354054628**Result** ✗ Failed

- Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #11 2015-07-20 11:45**MOT test number** 349271205256**Result** ✓ Passed

- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Notice** Child seat fitted not allowing full inspection of adult belt
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #10 2014-07-24 14:17**MOT test number** 647015004265**Result** ✓ Passed**MOT #9** 2014-07-17 12:16**MOT test number** 636038494171**Result** ✗ Failed

- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

**MOT #8** 2013-06-24 08:59**MOT test number** 266045373123**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #7** 2013-06-24 08:59**MOT test number** 269145373110**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2012-07-13 11:52**MOT test number** 789235592198**Result** ✓ Passed**Notice** Rear tyres wrong size to front**MOT #5** 2012-07-13 11:52**MOT test number** 249075292114**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Rear tyres wrong size to front**MOT #4** 2011-07-19 16:44**MOT test number** 539200201293**Result** ✓ Passed

**MOT #3** 2011-07-19 12:50**MOT test number** 979600101249**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Front coil spring fractured (2.4.C.1a)**MOT #2** 2010-05-12 11:48**MOT test number** 571802330128**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2010-05-12 11:48**MOT test number** 190172330185**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
9 January 2024

✓

MOT

Expires:
3 November 2024

Tax status	Expired at 9 January 2024
Days left	110 days too late
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KR07UAJ
Plate since	2024-03-29
Current registration	KR07UAJ
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-05-25
Last registration	2023-10-25
Complete history	See info



Registration #1	2007-05-25	26 mi
Registration #2	2010-05-12	35.402 mi
Registration #3	2011-07-19	37.506 mi
Registration #4	2011-07-19	37.506 mi
Registration #5	2012-07-13	38.066 mi
Registration #6	2013-06-24	39.993 mi
Registration #7	2014-07-17	42.034 mi
Registration #8	2014-07-24	42.054 mi
Registration #9	2015-07-20	44.290 mi
Registration #10	2016-07-11	48.198 mi
Registration #11	2016-07-11	48.198 mi
Registration #12	2016-07-11	48.198 mi
Registration #13	2016-07-11	48.198 mi
Registration #14	2016-07-11	48.198 mi
Registration #15	2016-07-11	48.198 mi
Registration #16	2016-07-11	48.198 mi
Registration #17	2016-07-11	48.198 mi
Registration #18	2016-07-11	48.198 mi
Registration #19	2016-07-11	48.198 mi
Registration #20	2016-07-11	48.198 mi
Registration #21	2016-07-11	48.198 mi
Registration #22	2016-07-11	48.198 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1662 mm
Height	1610 mm
Length	3731 mm
Wheel base	2315 mm
Kerb weight	1216 kg
Max. allowed weight	1596 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	FX6D2760602