



report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2016
Top speed	98 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 2

Date	2023-01-31
Pictures	25
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2022-02-10
Pictures	12
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2025-03-06
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	24
Total items failed	1

MOT #9	2024-03-07 13:49
MOT test number	447415841983
Result	✓ Passed
Next expiry date	2025-03-06

MOT #8	2024-03-05 16:47
MOT test number	562752876370
Result	✗ Failed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn edge (5.2.3 (e))
- MAJOR** Nearside Obligatory mirror insecure (3.3 (b) (ii))
- MAJOR** Offside Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Nearside Body component damaged and likely to cause injury Door moulding insecure (6.2.1 (a) (i))
- MAJOR** Brake pedal anti-slip provision missing (1.1.2 (c))

MOT #7	2023-03-03 13:01
MOT test number	270123611849
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2023-03-03 11:36**MOT test number** 663111188492**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2022-07-15 14:07**MOT test number** 896767659265**Result** ✓ Passed**MOT #4** 2021-08-31 16:23**MOT test number** 696710021134**Result** ✓ Passed**Advice** Front Macpherson strut pin or bush worn but not resulting in excessive movement both upper top mounting bearings are noisy (5.3.4 (a) (i))**MOT #3** 2020-08-29 08:13**MOT test number** 533759549660**Result** ✓ Passed**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing inner sidewall perished (5.2.3 (d) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing inner sidewall perished (5.2.3 (d) (ii))

**MOT #2**

2020-08-29 08:13

MOT test number

768805895299

Result**✗ Failed****Advice** Nearside Front Tyre slightly damaged/cracking or perishing inner sidewall perished (5.2.3 (d) (ii))**Pass with rectification** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing inner sidewall perished (5.2.3 (d) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #1**

2019-08-01 10:56

MOT test number

340365113282

Result**✓ Passed****Advice** Spare tyre defective**Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
6 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	6 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2023-03-28
Current registration	XXXXX
Plate since	2023-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-09-01
Last registration	2024-03-07
Complete history	See info



Registration #1	2016-09-01	27 mi
Registration #2	2019-08-01	63.384 mi
Registration #3	2020-08-29	75.327 mi
Registration #4	2020-08-29	75.327 mi
Registration #5	2021-08-31	85.919 mi
Registration #6	2022-08-31	96.511 mi
Registration #7	2023-08-31	107.103 mi
Registration #8	2023-08-31	107.103 mi
Registration #9	2023-08-31	107.103 mi
Registration #10	2023-08-31	107.103 mi
Registration #11	2023-08-31	107.103 mi
Registration #12	2024-03-07	117.695 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Wheel base	3105 mm
Kerb weight	1345 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2

Engine number	5889746
---------------	---------