




report date: 2024-03-28

General information

Make	KIA
Model	CARENS GS
Colour	Blue
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	157 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.2 mpg
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-08
Pictures	1



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-21
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	31
Total items failed	5

MOT #14	2023-09-14 13:26
MOT test number	223978766730
Result	✓ Passed
Next expiry date	2024-09-21
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Valve stem slightly damaged off side and near side cracked and perishing (5.2.3 (j))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Obligatory mirror slightly loose rear view (3.3 (b) (i))
Advice	Rear Coil spring corroded off side and near side (5.3.1 (b) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Valve stem slightly damaged (5.2.3 (j))

**MOT #13**

2023-09-13 11:20

**MOT test number**

186664612060

**Result****✗ Failed****Advice** Front Valve stem slightly damaged off side and near side cracked and perishing (5.2.3 (j))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Valve stem slightly damaged (5.2.3 (j))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Obligatory mirror slightly loose rear view (3.3 (b) (i))**Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Coil spring corroded off side and near side (5.3.1 (b) (i))**MOT #12**

2022-09-22 10:01

**MOT test number**

497136244736

**Result****✓ Passed****Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear wiper blade deteriorated**Advice** Nearside Front Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge and cracking evident in tread area (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge very close (5.2.3 (e))

**MOT #11** 2021-07-07 15:07**MOT test number** 139259972469**Result** ✓ Passed**MOT #10** 2021-07-07 15:07**MOT test number** 505565759885**Result** ✗ Failed**Pass with rectification** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #9** 2020-08-20 10:50**MOT test number** 947634505991**Result** ✓ Passed**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #8** 2019-03-26 17:15**MOT test number** 802878904444**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #7** 2018-04-05 08:59**MOT test number** 941956266714**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit on edge (4.1.E.1)**Advice** Light cracking/perishing in rear tyres

**MOT #6** 2017-04-03 09:18**MOT test number** 434909832981**Result** ✓ Passed**MOT #5** 2017-03-31 15:42**MOT test number** 681142295079**Result** ✗ Failed**Fail** Nearside Front Brake hose seriously damaged (found during steering lock to lock check) (2.2.D.2b)**MOT #4** 2016-04-08 09:28**MOT test number** 216907986628**Result** ✓ Passed**MOT #3** 2015-05-06 11:21**MOT test number** 736246225140**Result** ✓ Passed**Notice** Offside front top mount bearing noisy but has no play**MOT #2** 2014-05-07 11:02**MOT test number** 817297224147**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-05-08 11:57**MOT test number** 217918623410**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
21 September 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	21 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-05-11
Last registration	2023-09-14
Complete history	<a href="#">See info</a>



Registration #1	2010-05-11	17 mi
Registration #2	2013-05-08	21.893 mi
Registration #3	2014-05-07	29.181 mi
Registration #4	2015-05-06	35.780 mi
Registration #5	2016-04-08	43.683 mi
Registration #6	2017-03-31	51.149 mi
Registration #7	2017-04-03	51.150 mi
Registration #8	2018-04-05	57.725 mi
Registration #9	2019-05-07	65.377 mi
Registration #10	2020-05-07	73.029 mi
Registration #11	2021-05-07	80.681 mi
Registration #12	2022-05-07	88.333 mi
Registration #13	2023-05-07	95.985 mi
Registration #14	2024-05-07	103.637 mi
Registration #15	2025-05-07	111.289 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1700 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1450 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FC8H600396