




report date: 2024-03-28

General information

Make	FORD
Model	FIESTA TITANIUM
Colour	Black
Year of manufacture	2010
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E





## Internet history

### Entry 2

Date	2022-12-02
Pictures	20
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-01-30
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



**MOT history**

<b>MOT expiry date</b>	2024-12-20
<b>MOT pass rate</b>	73 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	4
<b>Total advice items</b>	40
<b>Total items failed</b>	9

**MOT #15** 2023-12-05 12:38

**MOT test number** 243649050289

**Result** ✓ Passed

**Next expiry date** 2024-12-20

**Advice** Fuel Pipe/s corroded



MOT #14 2022-12-21 13:45

MOT test number 510455225571

Result ✔ Passed

- Advice** Front Exhaust silencer slightly loose Exhaust flexi. (8.1.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Direction indicator lens defective which has no effect on emitted light Water in repeater lens. (4.4.1 (b) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Fuel lines slightly corroded.
- Advice** Offside Rear Outer Tyre slightly damaged/cracking or perishing Sidewall. (5.2.3 (d) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #13 2022-01-21 15:40

MOT test number 893200517737

Result ✔ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))



<b>MOT #12</b>	2022-01-21 14:13
<b>MOT test number</b>	430413005246
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Fail</b>	Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))
<b>Advice</b>	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Fail</b>	Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))

<b>MOT #11</b>	2021-01-25 12:01
<b>MOT test number</b>	967545400811
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2019-12-04 12:26
<b>MOT test number</b>	260076032839
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #9 2019-12-04 09:48

MOT test number 318847152801

Result ✗ Failed

- Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension component ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Bonnet cannot be secured in the closed position (3.1 (b) (i))

MOT #8 2018-10-03 14:26

MOT test number 175661317436

Result ✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear coil springs corroded
- Advice** Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Nearside Rear tyre showing signs of age
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front bumper damaged
- Advice** Fuel light on



<b>MOT #7</b>	2018-10-03 14:06
<b>MOT test number</b>	752396235853
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Rear Seat belt slightly damaged (7.1.2 (b) (i))
<b>Advice</b>	Nearside Rear tyre showing signs of age
<b>Advice</b>	Front bumper damaged
<b>Fail</b>	Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
<b>Advice</b>	Fuel light on
<b>Advice</b>	Rear coil springs corroded
<b>Fail</b>	Driver's view of the road through the swept area of the windscreen materially affected by an obstruction air freshners on interior mirror (3.1 (a) (ii))

<b>MOT #6</b>	2017-09-06 09:35
<b>MOT test number</b>	132034047716
<b>Result</b>	✓ Passed

<b>MOT #5</b>	2017-09-06 08:24
<b>MOT test number</b>	907327555812
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Stop lamp not working (1.2.1b)

<b>MOT #4</b>	2016-08-18 15:07
<b>MOT test number</b>	903628799849
<b>Result</b>	✓ Passed



**MOT #3** 2015-08-19 07:49

**MOT test number** 330671155995

**Result** ✓ Passed

**MOT #2** 2014-08-21 15:56

**MOT test number** 197613334252

**Result** ✓ Passed

**MOT #1** 2013-08-20 14:05

**MOT test number** 549072333280

**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
20 December 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	20 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>YX11 X</b>
Plate since	2019-09-29
Current registration	<b>YX11 X</b>
Plate since	2019-09-29

More info >



**Finance check**

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	18
<b>First mileage registration</b>	2010-09-09
<b>Last registration</b>	2023-12-05
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2010-09-09	16 mi
<b>Registration #2</b>	2013-08-20	9.683 mi
<b>Registration #3</b>	2014-08-21	13.023 mi
<b>Registration #4</b>	2015-08-19	15.480 mi
<b>Registration #5</b>	2016-08-18	18.241 mi
<b>Registration #6</b>	2017-09-06	29.569 mi
<b>Registration #7</b>	2017-09-06	29.569 mi
<b>Registration #8</b>	2018-10-03	42.351 mi
<b>Registration #9</b>	2018-10-03	42.351 mi
<b>Registration #10</b>	2019-09-09	55.277 mi
<b>Registration #11</b>	2019-09-09	55.277 mi
<b>Registration #12</b>	2019-09-09	55.277 mi
<b>Registration #13</b>	2019-09-09	55.277 mi
<b>Registration #14</b>	2019-09-09	55.277 mi
<b>Registration #15</b>	2019-09-09	55.277 mi
<b>Registration #16</b>	2019-09-09	55.277 mi
<b>Registration #17</b>	2019-09-09	55.277 mi
<b>Registration #18</b>	2019-09-09	55.277 mi

[More info >](#)



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	9E63133