



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS TDI SPORT 5 STR
Colour	Black
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-15
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-20
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	26
Total items failed	10

MOT #19	2023-12-21 12:43
MOT test number	654029442086
Result	✓ Passed
Next expiry date	2024-12-20
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #18	2023-12-21 09:23
MOT test number	355852240444
Result	✗ Failed
Fail	Offside Front Direction indicator incorrect colour Discoloured (4.4.3 (a))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Engine coolant low
Fail	Offside Front Headlamp light intensity severely reduced (4.1.4 (a))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #17** 2022-09-29 11:26**MOT test number** 154420834993**Result** ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))**MOT #16** 2021-10-13 13:52**MOT test number** 382791941156**Result** ✓ Passed**MOT #15** 2021-10-13 13:52**MOT test number** 611087910599**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**Pass with rectification** Front Windscreen washer not working (3.5 (a))**MOT #14** 2020-09-28 11:59**MOT test number** 971231945595**Result** ✓ Passed**Advice** Nearside Front Inner Play in steering rack inner joint(s)**MOT #13** 2019-09-28 12:36**MOT test number** 181928711462**Result** ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Advice** Offside Rear Nail in tyre

**MOT #12** 2019-09-28 11:43**MOT test number** 614178430734**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Play in steering rack inner joint(s)**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #11** 2018-09-29 11:34**MOT test number** 385688038018**Result** ✓ Passed**Advice** Offside Front Play in steering rack inner joint(s)**MOT #10** 2017-09-25 15:51**MOT test number** 626761245489**Result** ✓ Passed**MOT #9** 2017-03-28 15:12**MOT test number** 148427742762**Result** ✓ Passed**MOT #8** 2016-03-29 15:53**MOT test number** 309064532853**Result** ✓ Passed

**MOT #7** 2016-03-29 10:56**MOT test number** 666487003206**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2015-07-31 15:17**MOT test number** 907012615241**Result** ✓ Passed**MOT #5** 2015-07-31 12:50**MOT test number** 925902715268**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-08-01 12:29**MOT test number** 655623914210**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #3** 2013-07-25 13:06**MOT test number** 596676703216**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-07-24 14:21**MOT test number** 745416802234**Result** ✓ Passed**Notice** O/s/f tyre worn inner edge getting low**MOT #1** 2012-07-24 14:21**MOT test number** 366476502447**Result** ✗ Failed**Notice** O/s/f tyre worn inner edge getting low**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
20 December 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 RJ09WWS
Plate since	2024-03-29
Current registration	 RJ09WWS
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-07-27
Last registration	2023-12-21
Complete history	See info



Registration #1	2009-07-27	12 mi
Registration #2	2012-07-24	28.977 mi
Registration #3	2013-07-25	41.137 mi
Registration #4	2014-08-01	52.354 mi
Registration #5	2015-07-31	64.369 mi
Registration #6	2015-07-31	64.369 mi
Registration #7	2016-03-29	71.411 mi
Registration #8	2016-03-29	71.411 mi
Registration #9	2017-03-28	74.700 mi
Registration #10	2017-09-25	76.060 mi
Registration #11	2018-03-29	76.060 mi
Registration #12	2018-03-29	76.060 mi
Registration #13	2018-03-29	76.060 mi
Registration #14	2018-03-29	76.060 mi
Registration #15	2018-03-29	76.060 mi
Registration #16	2018-03-29	76.060 mi
Registration #17	2018-03-29	76.060 mi
Registration #18	2018-03-29	76.060 mi
Registration #19	2018-03-29	76.060 mi
Registration #20	2018-03-29	76.060 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1561 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKD C72007