



AU62LZR

report date: 2024-03-28

General information

Make	MINI
Model	MINI (R60) ONE D
Colour	Black
Year of manufacture	2012
Top speed	106 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	C






Internet history

Entry 2


Date	2022-02-04
Pictures	16
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-03
Pictures	7
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-23
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	10

MOT #12	2024-03-01 07:50
MOT test number	910402413732
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Wear to rear D rubbers

MOT #11	2023-03-22 15:47
MOT test number	347877711412
Result	✓ Passed
Advice	O/s/f tyre's heavy inner edge wear
Advice	Wear to rear anti roll bar D rubbers

MOT #10	2022-03-02 13:27
MOT test number	657803232264
Result	✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2021-03-24 14:24
MOT test number	198921649588
Result	✓ Passed

**MOT #8** 2021-03-24 14:24**MOT test number** 319897351839**Result** ✗ Failed

Pass with rectification Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #7 2019-06-28 14:02**MOT test number** 980853315512**Result** ✓ Passed**MOT #6** 2019-06-28 12:04**MOT test number** 344277794058**Result** ✗ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #5 2018-07-14 10:59**MOT test number** 703912915513**Result** ✓ Passed

**MOT #4** 2017-07-06 12:53**MOT test number** 385844935870**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2017-07-05 11:17**MOT test number** 223568735179**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber mounting deteriorated resulting in excessive movement wishbone rear mount (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Both front tyres worn close to cords on inner and outer edges**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Engine bay covers and under trays fitted obscuring some components**Fail** Offside Front Suspension arm rubber mounting deteriorated resulting in excessive movement wishbone rear mount (2.4.G.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Wiper blades deteriorating**MOT #2** 2016-07-09 14:52**MOT test number** 265472370758**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2015-06-14 11:58**MOT test number** 335295665158**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
23 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	23 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-09-14
Last registration	2024-03-01
Complete history	See info



Registration #1	2012-09-14	27 mi
Registration #2	2015-06-14	29.261 mi
Registration #3	2016-07-09	39.204 mi
Registration #4	2017-07-05	52.812 mi
Registration #5	2017-07-06	52.820 mi
Registration #6	2018-07-14	70.718 mi
Registration #7	2019-06-28	86.340 mi
Registration #8	2019-06-28	86.340 mi
Registration #9	2019-06-28	86.340 mi
Registration #10	2019-06-28	86.340 mi
Registration #11	2019-06-28	86.340 mi
Registration #12	2019-06-28	86.340 mi
Registration #13	2019-06-28	86.340 mi
Registration #14	2019-06-28	86.340 mi
Registration #15	2019-06-28	86.340 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

73288322