



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	GOLF TDI SE
Colour	Grey
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-13
Pictures	28
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-07
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	27
Total items failed	3

MOT #16	2023-06-24 07:44
MOT test number	599150783388
Result	✓ Passed
Next expiry date	2024-07-07

MOT #15	2022-07-08 08:02
MOT test number	363266261366
Result	✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Brake disc worn, pitted or scored, but not seriously weakened bothside rear badly corroded. (1.1.14 (a) (ii))

MOT #14	2021-06-30 08:08
MOT test number	326714085646
Result	✓ Passed

**MOT #13**

2021-06-28 11:47

MOT test number

203988346979

Result**✗ Failed****Pass with rectification** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged (5.2.3 (d) (ii))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #12**

2020-06-26 13:52

MOT test number

415436096909

Result**✓ Passed****Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11**

2020-06-20 10:28

MOT test number

546059297106

Result**✗ Failed****DANGEROUS** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MAJOR** Offside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Central Exhaust mounting defective (6.1.2 (a))

**MOT #10** 2019-07-05 07:29**MOT test number** 936252282511**Result** ✓ Passed

- Advice** Oil leak, but not excessive Engine oil (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Rear tyre tread starting to crack and perish

MOT #9 2018-06-29 11:47**MOT test number** 752430325009**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Inner faces (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Minor** Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8 2017-07-06 15:09**MOT test number** 785986364723**Result** ✓ Passed

**MOT #7** 2017-07-06 13:45**MOT test number** 218185345854**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**MOT #6** 2016-12-19 12:10**MOT test number** 779078233765**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2015-12-16 12:22**MOT test number** 338404776479**Result** ✓ Passed**MOT #4** 2014-12-22 12:35**MOT test number** 459176254423**Result** ✓ Passed**MOT #3** 2013-12-11 12:48**MOT test number** 456015543463**Result** ✓ Passed**MOT #2** 2012-12-12 12:59**MOT test number** 176907142348**Result** ✓ Passed



MOT #1	2011-12-12 16:50
MOT test number	405506441306
Result	✓ Passed
Advice	Front Suspension arm has slight play in a pin/bush (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BD58UWY
Plate since	2019-06-29
Current registration	 BD58UWY
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-12-29
Last registration	2023-06-24
Complete history	See info



Registration #1	2008-12-29	16 mi
Registration #2	2011-12-12	41.207 mi
Registration #3	2012-12-12	47.174 mi
Registration #4	2013-12-11	55.644 mi
Registration #5	2014-12-22	64.093 mi
Registration #6	2015-12-16	71.842 mi
Registration #7	2016-12-19	79.539 mi
Registration #8	2017-07-06	82.384 mi
Registration #9	2017-07-06	82.384 mi
Registration #10	2018-06-20	85.377 mi
Registration #11	2019-06-20	88.377 mi
Registration #12	2020-06-20	91.377 mi
Registration #13	2021-06-20	94.377 mi
Registration #14	2022-06-20	97.377 mi
Registration #15	2023-06-20	100.377 mi
Registration #16	2024-06-20	103.377 mi
Registration #17	2025-06-20	106.377 mi
Registration #18	2026-06-20	109.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1517 mm
Length	4774 mm
Wheel base	2709 mm
Kerb weight	1715 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKP 293807