

Ford



## General information

| Make                | FORD               |
|---------------------|--------------------|
| Model               | TRANSIT 310 LR P/V |
| Colour              | White              |
| Year of manufacture | 2015               |
| Top speed           | 93 mph             |
| Gearbox             | 6 speed Manual     |

# Engine & fuel consumption

| Power                   | 74 kW / 101 HP / 123 BHP |
|-------------------------|--------------------------|
| Max. torque             | 310 Nm at 1.300 rpm      |
| Engine capacity         | 2.198 сс                 |
| Cylinders               | 4                        |
| Fuel type               | Diesel                   |
| Consumption city        | 39.2 mpg                 |
| Consumption extra urban | 44.1 mpg                 |
| Consumption combined    | 42.2 mpg                 |
| CO2 emission            | 178 g/km                 |
| CO2 label               | 1                        |







### Internet history


Entry 2

Date Pictures 2021-06-23

50

Listing price

View report



source: cargurus.co.uk

### Entry 1

Date

Pictures

Listing price

2021-06-23

66





source: autotrader.co.uk







# MOT history

| MOT expiry date    | 2025-04-08 |
|--------------------|------------|
| MOT pass rate      | 78 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 2          |
| Total advice items | 17         |
| Total items failed | 2          |

| MOT #9         |   | 2024-04-09 12:24   |
|----------------|---|--------------------|
| MOT test       | number  | 268243037591       |
| Result         |   | 🗸 Passed           |
| Next exp       | iry date  | 2025-04-08         |
| Minor          | Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))        |                    |
| Minor          | Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |                    |
| Advice<br>(i)) | Offside Front Suspension arm pin or bush worn but not resulting in excessive mo         | ovement (5.3.4 (a) |

| MOT #8             |  | 2024-04-08 12:54           |
|--------------------|--|----------------------------|
| MOT test num       | ber  | 592542382185               |
| Result             |  | 🗙 Failed                   |
| Minor From         | t Windscreen damaged but not adversely affecting driver's view (3.2      | 2 (a) (i))                 |
| Advice Off<br>(i)) | side Front Suspension arm pin or bush worn but not resulting in exce     | essive movement (5.3.4 (a) |
| Fail Offside       | e Front Tyre has ply or cords exposed (5.2.3 (d) (ii))                   |                            |
| Minor Offs         | ide Front Anti-roll bar ball joint dust cover severely deteriorated (5.3 | .4 (b) (i))                |
| Advice Ne          | arside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))     |                            |





| MOT #7   | 2023-03-31 09:42      |
|--|-----------------------|
| MOT test number  | 136395135327          |
| Result   | ✓ Passed              |
| Advice Offside Front Suspension arm pin or bush worn but not resulting in e. (5.3.4 (a) (i)) | xcessive movement arm |
| MOT #6   | 2022-03-24 17:25      |

| MOT test | number   | 936490022474 |
|----------|--|--------------|
| Result   |  | ✓ Passed     |
| Advice   | Offside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) |              |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |              |

| MOT #5   | 2021-0.  | 3-08 10:03 |
|----------|--|------------|
| MOT test | t number 4140  | 08986974   |
| Result   |  | ✓ Passed   |
| Minor    | Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |            |
| Advice   | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                                |            |

| MOT #4          | 2020-03-09 10:04 |
|-----------------|------------------|
| MOT test number | 602917548899     |
| Result          | ✓ Passed         |

| МОТ #3  | 2020-03-06 12:36 |
|---|------------------|
| MOT test number   | 215206722333     |
| Result  | 🗙 Failed         |
| Advice Front Service brake binding but not excessively (1.2.1 (f))  |                  |
| Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))                          |                  |
| <b>Fail</b> Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) |                  |
| Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))  |                  |





| MOT #2   | 2019-03-15 10:09 |
|--|------------------|
| MOT test number  | 776505756929     |
| Result   | ✓ Passed         |
|  |                  |
| MOT #1   | 2018-03-09 12:01 |
| MOT test number  | 568006758469     |
| Result   | ✓ Passed         |
| Advice Front Brake pad(s) wearing thin both front (3.5.1g)       |                  |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) |                  |



Tax & MOT check

| ✓                | ✓                  |
|------------------|--------------------|
| Taxed            | MOT                |
| Tax due:         | Expires:           |
| 1 June 2024      | 8 April 2025       |
| Tax status       | Valid until 1 June |
| Days left        | 32                 |
| MOT expiry date  | 8 April 2025       |
| Full MOT history | See MOT history    |

## Tax calculation

| Vehicle class             | 39         |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months)  | £ 151,25,- |





### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |       |
|----------|--|-------|
| Date     |  |       |
| Category |  | ARMP  |
| Туре     |  |       |
| Damage 2 |  | AMPLE |
|          | E E  | AT I  |
| Date     |  | *     |
| Category | AMA  |       |
| Туре     | No. Contraction of the second se |       |

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec |             |
|--|-------------|
| ***********  |             |
| ********   |             |
| ******   |             |
| ***********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
|  |             |
| Current registration   |             |
| Current registration<br>Pate since   |             |





### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info  $\rightarrow$ 





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 12         |
| First mileage registration | 2015-03-25 |
| Last registration          | 2024-04-09 |
| Complete history           | See info   |



| Registration #1                    | 2015-03-25 | 29 mi   |
|------------------------------------|------------|---|
| Registration #2                    | 2018-03-09 | 31.995 mi   |
| Registration #3                    | 2019-03-15 | 45.010 mi   |
| Registration #4                    | 2020-03-06 | 59.639 mi   |
| Registration #5                    | 2020-03-09 | 59.641 mi   |
| Registration #6                    | 2021-03-08 | 71.455 mi   |
|                                    |            |   |
| Registration #7                    |            | 11.777 mi   |
| Registration #7<br>Registration #8 |            | 00.000 est  |
|                                    |            | 00.000 ees<br>00.000 ees<br>00.000 ees                            |
| Registration #8                    |            | 00.000 est<br>0.000 est<br>00.000 est<br>00.000 est               |
| Registration #8<br>Registration #9 |            | 00.000 460<br>0.000 460<br>00.000 460<br>00.000 460<br>00.000 460 |

More info >





## Car features

| S0225  | Air conditioning |
|--------|------------------|
| S0295  |                  |
| 50482  |                  |
| \$0501 |                  |
| S0566  |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 84%             |
| Children       | 90%             |
| Pedestrian     | 48%             |
| Safety systems | 71%             |
| Overall rating | 76%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 2290 mm          |
| Height                            | 1972 mm          |
| Length                            | 4972 mm          |
| Wheel base                        | 3300 mm          |
| Kerb weight                       | 1817 kg          |
| Max. allowed weight               | 3100 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 80               |
| Fuel delivery                     | Direct Injection |
| Number of seats                   | 3                |
| Number of axles<br>CarCheck.co.uk | 2 page 12/12     |