





## General information

Make	RENAULT
Model	KANGOO EXPRESSION DCI 86 E4
Colour	Blue
Year of manufacture	2005
Top speed	98 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	83 BHP
Max. torque	200 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	57.6 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E







AA

You're in safe hands This dealer has signed our Dealer Promise

## Internet history


Entry 1

Date Pictures 2022-03-12

12

Listing price

View report



source: cargurus.co.uk





# MOT history

MOT expiry date	2024-03-16
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	24
Total items failed	11

MOT #21		2023-03-17 11:51
MOT test	number	297333358656
Result		✓ Passed
Next expiry date 2024-03		2024-03-16
Advice	Offside Front Inner Road wheel slightly distorted Inner edge a little buckl	ed (5.2.2 (c) (i))
Advice	Front Battery clamp missing but battery is within a compartment.	

МОТ #20	2022-03-14 12:30
MOT test number	455150199052
Result	✓ Passed
Advice Nearside Play in steering rack inner joint(s)	
Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))	
Minor Windscreen damaged but not adversely affecting driver's view Chip (3.2 (a) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge Close (5.2.3 (e))	

MOT #19	2021-05-14 07:26
MOT test number	729073391904
Result	✓ Passed





MOT #18	2020-03-24 16:13
MOT test number	502525965870
Result	✓ Passed
MOT #17	2020-03-24 10:07
MOT test number	608483551725
Result	🗙 Failed
<b>Fail</b> Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
<b>Fail</b> Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
MOT #16	2019-03-23 10:35
MOT test number	239960618039

✓ Passed

MOT #15	2018-03-21 10:58
MOT test number	408628274908
Result	✓ Passed

MOT #14	2017-03-30 08:51
MOT test number	749959365173
Result	✓ Passed
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	

Result



<b>GY05FHN</b>
report date: 2024-03-29

MOT #13	2017-03-23 12:48
MOT test number	920297319525
Result	🗙 Failed
Fail         Rear Exhaust system not adequately supported (7.1.1)	
Advice Front brake disc worn, pitted or scored, but not seriously weakened both side	es (3.5.1i)
Fail         Registration plate lamp not working (1.1.C.1d)	
FailFront Brakes imbalanced across an axle (3.7.B.5b)	
Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)	

MOT #12	2016-03-16 12:27
MOT test number	288074459120
Result	✓ Passed
Advice Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)	

MOT #11	2016-03-15 12:31
MOT test number	778930994888
Result	🗙 Failed
Advice       Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)         Fail       Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)	
MOT #10	2015-03-04 10:59

	2013 03 04 10.33
MOT test number	277713865077
Result	✓ Passed
Notice No smoke detected	





MOT #9		2014-03-05 11:26
MOT test	number	159894764025
Result		✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1	d)
Advice Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)		
(2.5.C.1a)		

MOT #8	2013-02-27 11:13
MOT test number	139768853088
Result	✓ Passed
<b>Advice</b> Brakes imbalanced requirements only just met. It would appear that the braki adjustment or repair. (3.7.B.5b)	ng system requires
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
<b>Notice</b> BOTH FRONT TYRES STARTING TO WEAR INNER & OUTER EDGE	

МОТ #7	2012-02-27 10:56
MOT test number	476108752019
Result	✓ Passed
<b>Notice</b> Front brake discs slightly worn	
MOT #6	2011-03-03 14.50

MOT #6	2011-03-03 14:59
MOT test number	777282161061
Result	✓ Passed
<b>Notice</b> Fornt brake discs in poor condistion	



G	105FHN
rej	oort date: 2024-03-29

MOT #5	2011-03-02 10:41
MOT test number	626561261030
Result	🗙 Failed
Fail         Front Windscreen washer provides insufficient washer liquid (8.2.3)	
Notice Fornt brake discs in poor condistion	
Fail         Offside Front Front constant velocity joint gaiter insecurely mounted to its house	sing (2.5.C.1a)

МОТ #4	2010-03-03 10:55
MOT test number	252862060076
Result	✓ Passed
Notice Near side outer door handle damaged	
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice Nail in offside rear tyre	

MOT #3	2009-02-26 16:11
MOT test number	971007459046
Result	✓ Passed

MOT #2	2009-02-26 11:31
MOT test number	932147059088
Result	🗙 Failed
<b>Fail</b> Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)	
Fail         Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice N/S/F tyre sidewall cut	
<b>Fail</b> Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	





MOT #1	2008-03-05 11:06
MOT test number	102445468419
Result	✓ Passed



GY05FHN report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 2 April 2024	<b>X</b> <b>MOT</b> Expired: 16 March 2024
Tax status	Expired at 2 April 2024
Days left	28 days too late
MOT expiry date	16 March 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	 
Category	 AMPL
Туре	

#### Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second se	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Reduction a	
Plane anna	
Current registration	
Current registration Plate since	





#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



GY05FHN report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-22
Last registration	2023-03-17
Complete history	<u>See info</u>



Registration #1	2005-03-22	27 mi
Registration #2	2008-03-05	16.299 mi
Registration #3	2009-02-26	21.819 mi
Registration #4	2009-02-26	21.819 mi
Registration #5	2010-03-03	26.188 mi
Registration #6	2011-03-02	31.569 mi
Registration #7	2011-03-03	31.576 mi
Registration #8	2012-02-27	36.034 mi
Registration #9	2013-02-27	42.270 mi
Registration #10	2014-03-05	46.364 mi
Registration #11	2015-03-04	52.239 mi
Registration #12	2016-03-15	56.979 mi
Registration #12	2016-03-15	
Registration #12 Registration #13	2016-03-15	
Registration #12 Registration #13 Registration #14	2016-03-15	
Registration #12 Registration #13 Registration #14 Registration #15	2016-03-15	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2016-03-15	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2016-03-15	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	2016-03-15	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	2016-03-15	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	2016-03-15	

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1672 mm
Height	1855 mm
Length	4035 mm
Wheel base	2605 mm
Kerb weight	1125 kg
Max. allowed weight	1630 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15