



PKIIMDN

report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D3 ES
Colour	Black
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg





Internet history

Entry 2

Date	2021-12-04
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-12-02
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history**

MOT #13	2023-01-19 16:14
MOT test number	897020932570
Result	✓ Passed
Next expiry date	2024-01-18
Minor	Position lamp incorrect colour both sides blue (4.2.3 (a) (i))
Advice	Rear tyres show evidence of fouling arches

MOT #12	2023-01-13 13:03
MOT test number	971649442444
Result	✗ Failed
Fail	Nearside Front Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated loss of grease (6.1.7 (g) (i))
Fail	Rear Direction indicator incorrect colour both sides (4.4.3 (a))
Advice	Rear tyres show evidence of fouling arches
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Fail	Offside Front Anti-roll bar linkage insecure and impairing directional stability (5.3.3 (a) (ii))
Minor	Position lamp incorrect colour both sides blue (4.2.3 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Registration plate lamp does not illuminate simultaneously with the position lamps both sides flashing (4.7.2 (a))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #11** 2022-01-11 12:02**MOT test number** 527293038359**Result** ✓ Passed**Advice** Brake disc worn, but not excessively Both rear (1.1.14 (a) (i))**MOT #10** 2022-01-11 12:02**MOT test number** 370586135714**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Brake disc worn, but not excessively Both rear (1.1.14 (a) (i))**MOT #9** 2021-01-29 16:08**MOT test number** 953393482929**Result** ✓ Passed**MOT #8** 2021-01-27 09:38**MOT test number** 286584380064**Result** ✗ Failed**Fail** Nearside Rear Inner Tyre has a lump, caused by separation or partial failure of its structure 205/50-17 (5.2.3 (d) (ii))**MOT #7** 2020-01-17 11:43**MOT test number** 769615536864**Result** ✓ Passed**MOT #6** 2019-02-12 09:47**MOT test number** 292441488480**Result** ✓ Passed

**MOT #5** 2018-02-05 13:51**MOT test number** 744721535813**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit Worn Inner Edge (4.1.E.1)**MOT #4** 2017-02-17 16:26**MOT test number** 592845011267**Result** ✓ Passed**MOT #3** 2016-05-18 08:26**MOT test number** 382513192299**Result** ✓ Passed**MOT #2** 2015-06-08 12:05**MOT test number** 818669155139**Result** ✓ Passed**MOT #1** 2014-06-11 11:14**MOT test number** 186442464119**Result** ✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-07-06
Last registration	2023-01-19
Complete history	See info



Registration #1	2011-07-06	24 mi
Registration #2	2014-06-11	29.558 mi
Registration #3	2015-06-08	38.440 mi
Registration #4	2016-05-18	46.602 mi
Registration #5	2017-02-17	52.838 mi
Registration #6	2018-02-05	60.484 mi
Registration #7	2019-02-12	76.878 mi
Registration #8	2020-01-17	89.480 mi
Registration #9	2020-05-20	95.377 mi
Registration #10	2020-05-20	95.377 mi
Registration #11	2020-05-20	95.377 mi
Registration #12	2020-05-20	95.377 mi
Registration #13	2020-05-20	95.377 mi
Registration #14	2020-05-20	95.377 mi
Registration #15	2020-05-20	95.377 mi
Registration #16	2020-05-20	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1504 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1012435