






report date: 2024-03-28

General information

Make	ТОУОТА
Model	COROLLA VERSO D-4D T SPIRIT
Colour	Blue
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	279 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	45.6 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 2

Date	2023-03-08
Pictures	1
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-05-21
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



RN05KMO report date: 2024-03-28

MOT history

MOT expiry date	2025-03-28
MOT pass rate	94 %
MOT passed	17
Failed MOT tests	1
Total advice items	33
Total items failed	2

MOT #18	2024-03-25 16:54
MOT test number	438645852674
Result	✓ Passed
Next expiry date	2025-03-28
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Front Headlamp lens slightly defective Both (4.1.1 (b) (i))	

MOT #17	2023-03-29 12:28
MOT test number	348187725993
Result	✓ Passed

MOT test number 47354523990	Nesuit V 1 disect		
MOT test number Result Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))			
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	MOT #16		2022-07-27 11:40
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	MOT test	number	473545239903
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	Result		✓ Passed
Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))	Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
	Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5	5.3.4 (b) (i))
	Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Advice Sub-frame corroded but not seriously weakened Front and Rear (5.3.3 (b) (i))	Advice	Sub-frame corroded but not seriously weakened Front and Rear (5.3.3 (b) (i)))

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Sub-frame corroded but not seriously weakened FRONT + REAR (5.3.3 (b) (i))

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2020-08-17 12:03
MOT test	number 954556124151
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge wearing on edges 205/55 16 (5.2.3 (e))
Advice	Corrosion on all suspension components
Advice	Offside Front Tyre worn close to legal limit/worn on edge wearing on edges 205/55 16 (5.2.3 (e))

MOT #13	2019-08-0	09 08:23
MOT test	number 48756	8585040
Result		✓ Passed
Advice	Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Inner Brake pad(s) wearing thin pads look to be wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #12 2018-07-25 14:15

MOT test number 770228135508

Result ✓ Passed

Advice Brake pad(s) wearing thin Advise Front inner brake pads look to be wearing low but they are not clearly visible during test (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, but not excessively Heavily worn & Lipped (1.1.14 (a) (i))

Advice Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Front Brake disc worn, but not excessively Heavily worn & Lipped (1.1.14 (a) (i))

Advice Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #11 2017-08-09 12:04

MOT test number 485154300370

Advice Engine bay covers & under trays fitted obscuring some testable components

Advice Offside Front Brake pad(s) wearing thin inner pad appears to be wearing thin but it is not clearly visible during test (3.5.1g)

Advice Advise Front wipers starting to lightly smear across windscreen

MOT #10 2016-08-10 10:08

MOT test number 171287078719

Result ✓ Passed

MOT #9 2015-08-05 09:20

MOT test number 137137215202

Result ✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/14



Notice

RN05KMO

report date: 2024-03-28

 MOT #8
 2014-08-18 15:48

 MOT test number
 497250534261

 Result
 ✓ Passed

 MOT #7
 2013-08-08 15:34

 MOT test number
 397120123240

 Result
 ✓ Passed

Both front tyres heavily worn on inner edges

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #5	2011-08-05 10:38
MOT test number	236097011230
Result	✓ Passed
MOT #4	2010-08-17 14:55
MOT test number	162929520297
Result	✓ Passed
MOT #3	2009-08-06 16:23
MOT test number	870968119296
Result	✓ Passed

CarCheck.co.uk page 6/14



RN05KMO report date: 2024-03-28

MOT #2 2008-08-13 14:50

MOT test number 961536828219

MOT #1 2008-08-13 14:50

MOT test number 452766928283

Result X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	28 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NIE ZIIN
Plate since	
Current registration	NK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-08-03
Last registration	2024-03-25
Complete history	See info



Registration #1	2005-08-03	6 mi
Registration #2	2008-08-13	24.903 mi
Registration #3	2009-08-06	29.273 mi
Registration #4	2010-08-17	32.935 mi
Registration #5	2011-08-05	37.768 mi
Registration #6	2012-07-17	43.171 mi
Registration #7	2013-08-08	48.719 mi
Registration #8	2014-08-18	52.235 mi
Registration #9	2015-08-05	53.537 mi
Registration #10	2016-08-10	55.977 mi
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		9.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		77.777 au

More info >

CarCheck.co.uk page 13/14



RN05KMO report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
60501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles 2

Engine number 1CD0440382