



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 7 STR (90BHP)
Colour	Blue
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	210 Nm at 1.800 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-14
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-04-04
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	40
Total items failed	9

MOT #19 2023-03-30 15:38

MOT test number 358935669224

Result ✗ Failed

DANGEROUS Tyre tread depth below requirements of 1.6mm all (5.2.3 (e))

Advice Nearside Non obligatory mirror damaged

DANGEROUS Nearside Front Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired seal (6.2.2 (d) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #18 2022-04-05 11:37

MOT test number 601406641556

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Tyre worn close to legal limit/worn on edge all for tyres 3mm (5.2.3 (e))

Advice Rear al rear bushes deteriorating

Advice Offside Rear Nail in tyre

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Tyre worn close to legal limit/worn on edge both rears worn smooth on inner edge (5.2.3 (e))

**MOT #17** 2021-03-16 15:56**MOT test number** 274121659472**Result** ✓ Passed

- Advice** Rear surface corrosion on all rear suspension components
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #16 2021-03-15 17:07**MOT test number** 190954718880**Result** ✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Rear surface corrosion on all rear suspension components
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15 2019-11-21 09:45**MOT test number** 326586390136**Result** ✓ Passed

**MOT #14** 2018-08-21 09:40**MOT test number** 530140315297**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #13** 2017-08-08 12:40**MOT test number** 292191868415**Result** ✓ Passed**MOT #12** 2017-08-08 08:57**MOT test number** 715995420754**Result** ✗ Failed**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)**Fail** Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #11** 2016-08-17 13:38**MOT test number** 166696868617**Result** ✓ Passed**MOT #10** 2016-08-16 11:06**MOT test number** 375876813323**Result** ✗ Failed**Fail** Offside Rear Shock absorber has an excessively worn bush (2.7.4)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

**MOT #9** 2015-08-21 12:58**MOT test number** 898821788614**Result** ✓ Passed**Advice** Nearside front tyre wearing on outer edge**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside front tyre wearing on inner edge**MOT #8** 2014-08-11 11:51**MOT test number** 586793524232**Result** ✓ Passed**Notice** Offside and nearside rear shock absorber covers missing**MOT #7** 2013-08-19 12:16**MOT test number** 836461933281**Result** ✓ Passed**Notice** Offside and nearside rear shock absorber outer covers missing**Notice** Offside rear tyre wearing on inner edge**MOT #6** 2013-08-19 12:11**MOT test number** 629371733247**Result** ✗ Failed**Notice** Offside and nearside rear shock absorber outer covers missing**Notice** Offside rear tyre wearing on inner edge**Fail** Brakes imbalanced across an axle (3.7.B.5b)

**MOT #5** 2012-08-20 12:02**MOT test number** 775653632215**Result** ✓ Passed**Notice** Offside rear shock absorber cover missing**Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)**Notice** Nearside rear shock absorber cover missing**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2011-08-22 15:15**MOT test number** 859164431298**Result** ✓ Passed**MOT #3** 2011-08-19 12:08**MOT test number** 417461131264**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #2** 2010-08-18 11:52**MOT test number** 472270930202**Result** ✓ Passed**Notice** Offside and nearside rear shock absorber protective covers missing**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Dlight distortion on nearside rear tyre tread area**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)



MOT #1	2009-08-19 13:54
MOT test number	700801839291
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
6 April 2023

✕
MOT

Expired:
4 April 2023

Tax status	Expired at 6 April 2023
Days left	389 days too late
MOT expiry date	4 April 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

SE06VVZ	2019-01-01
SE06VVZ	2019-01-01
SE06VVZ	2019-01-01
SE06VVZ	2019-01-01
SE06VVZ	2019-01-01
SE06VVZ	2019-01-01
SE06VVZ	2019-01-01

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 SE06VVZ
Plate since	2019-01-01
Current registration	 SE06VVZ
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-08-22
Last registration	2023-03-30
Complete history	See info



Registration #1	2006-08-22	20 mi
Registration #2	2009-08-19	24.382 mi
Registration #3	2010-08-18	33.872 mi
Registration #4	2011-08-19	43.991 mi
Registration #5	2011-08-22	44.069 mi
Registration #6	2012-08-20	53.743 mi
Registration #7	2013-08-19	63.552 mi
Registration #8	2013-08-19	63.552 mi
Registration #9	2014-08-11	73.916 mi
Registration #10	2015-08-21	83.344 mi
Registration #11	2016-08-16	121.216 mi
Registration #12	2016-08-16	121.216 mi
Registration #13	2016-08-16	121.216 mi
Registration #14	2016-08-16	121.216 mi
Registration #15	2016-08-16	121.216 mi
Registration #16	2016-08-16	121.216 mi
Registration #17	2016-08-16	121.216 mi
Registration #18	2016-08-16	121.216 mi
Registration #19	2016-08-16	121.216 mi
Registration #20	2016-08-16	121.216 mi
Registration #21	2016-08-16	121.216 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4407 mm
Wheel base	2678 mm
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

BRU 097436