





General information

Make	HONDA
Model	ACCORD I-DTEC EX
Colour	Black
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 1

Date

Pictures

2022-04-17

20

Listing price

View report









source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-19
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	19
Total items failed	3

MOT #14	2023-10-23 11:35
MOT test number 746440641	
Result	
Next expiry date	2024-11-19
Advice Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #13		2022-10-22 11:14
MOT test	number	355416384603
Result		✓ Passed
Advice	Parking brake required effort only just met	
Advice	Front Exhaust has a minor leak of exhaust gases recommend attention (6.1.2 (a)))
Advice	Advice Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	



RE09POV
report date: 2024-03-28

MOT #12		2021-11-20 15:53
MOT test i	number	537074400011
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Anti-lock braking system component slightly damaged (1.6 (e))	
Advice (b))		
Advice	VSA light display indicating a fault	
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously reducin	ng light output (4.1.4

MOT #11	2020-11-05 17:21
MOT test number	440334940061
Result	✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in (a) (i))	n excessive movement (5.3.4
Advice Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in e	excessive movement (5.3.4 (a)

MOT #10	2019-05-01 15:05
MOT test number	374021234800
Result	✓ Passed

MOT #9	2019-05-01 15:05
MOT test number	448284932257
Result	× Failed
Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))	





MOT #8	2018-05-02 12:28
MOT test number	910251446491
Result	✓ Passed
MOT #7	2018-05-01 11:30
MOT test number	257200787619
Result	🗙 Failed
Fail Offside Rear reflector missing (1.5.1a)	
МОТ #6	2017-04-08 11:43
MOT test number	536103810838
Result	✓ Passed
Advice Tyre worn close to the legal limit both front (4.1.E.1)	
MOT #5	2016-04-15 14:19
MOT test number	864471970187
Result	✓ Passed
MOT #4	2015-04-20 11:10
MOT test number	725500515121
Result	✓ Passed
MOT #3	2014-04-16 11:12
MOT test number	448176904193
Result	✓ Passed
MOT #2	2013-04-23 17:30
MOT #2 MOT test number	247823013415
Result	✓ Passed
	•





MOT #1	2012-06-09 08:52
MOT test number	706471962163
Result	✓ Passed
Notice Nearside front tyre wearing on outer tread	



REO9POV report date: 2024-03-28

Tax & MOT check

✓ Taxed Tax due: 1 October 2024	MOT Expires: 19 November 2024
Tax status	Valid until 1 October
Days left	154
MOT expiry date	19 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this HONDA had different number pla	tes.
Number of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



REO9POV report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-11
Last registration	2023-10-23
Complete history	See info



Registration #1	2009-06-11	6 mi
Registration #2	2012-06-09	32.580 mi
Registration #3	2013-04-23	37.345 mi
Registration #4	2014-04-16	44.556 mi
Registration #5	2015-04-20	50.261 mi
Registration #6	2016-04-15	56.563 mi
Registration #7	2017-04-08	67.198 mi
Registration #8	2018-05-01	73.855 mi
Registration #9		11.117 es
Registration #9 Registration #10		11.777 es
-		01,000 est 01,000 est 01,000 est
Registration #10		01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11 Registration #12		01,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46
Registration #10 Registration #11 Registration #12 Registration #13		01,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46 0,000 46





Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Max. allowed weight	2030 kg
Additional information	
Additional information Fuel tank capacity	65 l
	65 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4