





report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/12



EJ62WYD

report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-27

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-07-07
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	11
Total items failed	5

MOT #13	2023-07-07 09:52
MOT test number	285534570234
Result	✓ Passed
Next expiry date	2024-07-07

MOT #12		2023-07-07 09:52
MOT test number		924229237239
Result		X Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOI #II		2022-07-04 10:43
MOT test	number	634170624203
Result		✓ Passed
MOT #10		2021-07-08 11:20
MOT test number 482620654175		
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.	3 (d) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing perishing (5.2.3	(d) (ii))

CarCheck.co.uk page 3/12



(b) (i))

EJ62WYD
report date: 2024-03-28

MOT #9 2020-10-12 10:25

MOT test number 895888445827

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

MOT #8 2019-10-28 15:24

MOT test number 698123434037

Result \(\sqrt{Passed} \)

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #7 2018-10-30 11:39

MOT test number 588005070353

Result \(\sqrt{Passed} \)

MOT #6 2018-10-30 11:39

MOT test number 918971536948

Result X Failed

Pass with rectification Front Registration plate insecure (0.1 (a))

MOT #5 2017-11-17 10:03

MOT test number 981330499815

Result \(\sqrt{Passed} \)

Advice Offside front tyre worn on shoulders

Advice Nearside rear tyre perished

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



X Failed

MOT #4 2016-11-18 12:38

MOT test number 277590380430

Advice Nearside Rear tyre perished

Result

MOT #3 2016-11-18 12:38

MOT test number 806844514327

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Nearside Rear tyre perished

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

MOT #2 2015-12-10 16:20

MOT test number 642614558463

Result ✓ Passed

MOT #1 2015-12-10 09:18

MOT test number 949944319437

Result X Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 July
Days left	62
MOT expiry date	7 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category


Type

Date

Damage 2

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	AND THE STATE OF T
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-11-30
Last registration	2023-07-07
Complete history	See info



Registration #1	2012-11-30	24 mi
Registration #2	2015-12-10	11.761 mi
Registration #3	2015-12-10	11.761 mi
Registration #4	2016-11-18	16.186 mi
Registration #5	2016-11-18	16.186 mi
Registration #6	2017-11-17	20.143 mi
Registration #7	2018-10-30	24.882 mi
Registration #8	2018-10-30	24.882 mi
Registration #9		11.777 mi
Registration #10		71.777 es
Registration #11		9.39 es
Registration #12		11.777 es
Registration #13		9.39 es
Registration #14		0.00 44
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	202373K

CarCheck.co.uk page 12/12