





report date: 2024-03-28

General information

Make	NISSAN
Model	MICRA VISIA
Colour	White
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-14


Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	16
Total items failed	6

MOT #10		2023-05-03 09:14
MOT test	number	342354708035
Result		✓ Passed
Next exp	iry date	2024-05-02
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge Tyre bold o	n outer edge (5.2.3 (e))
Advice	Rear Inner Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))	
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2023-05-03 09:14 **MOT** test number 467778303436 Result × Failed Minor Front Windscreen wiper blade defective (3.4 (b) (i)) **Advice** Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii)) Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge Tyre bold on outer edge (5.2.3 (e)) Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** Rear Inner Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))

MOT #8

MOT test number

762040883655

Result

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

MOT test number

2021-04-27 14:08

Result

✓ Passed

MOT test number

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5

MOT test number

450525650291

Result

Advice Rear wiper missing

MOT #4 2019-03-12 10:47 **MOT test number** 613193426229 Result ✓ Passed **MOT** #3 2019-03-11 14:56 **MOT** test number 759899906668 Result × Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail

MOT #2

MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2017-02-11 09:32

MOT test number 550618061789

Result ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	2 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



GU14BNZ report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-17
Last registration	2023-05-03
Complete history	See info



Registration #1	2014-03-17	18 mi
Registration #2	2017-02-11	16.724 mi
Registration #3	2018-03-07	20.036 mi
Registration #4	2019-03-11	22.257 mi
Registration #5	2019-03-12	22.257 mi
Registration #6	2020-01-13	26.104 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.70 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12