



RENAULT



MX59RRZ

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	White
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-08
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-22
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	46
Total items failed	17

MOT #19	2023-06-23 11:07
MOT test number	600784546213
Result	✓ Passed
Next expiry date	2024-06-22

MOT #18	2023-06-22 12:14
MOT test number	727838961933
Result	✗ Failed
<div><div>Advice</div> Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	
<div><div>Fail</div> Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div>	
<div><div>Fail</div> Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))</div>	
<div><div>Advice</div> Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	
<div><div>Fail</div> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))</div>	

**MOT #17**

2022-11-02 08:19

**MOT test number**

221355038618

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16**

2022-11-02 08:19

**MOT test number**

473469706404

**Result**

✗ Failed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2021-11-10 09:02

**MOT test number**

701708022766

**Result**

✓ Passed

- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #14** 2021-11-09 15:25**MOT test number** 155767972807**Result** ✗ Failed

- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Front Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Nearside Front Track rod end modification unsafe (2.1.3 (f) (i))

**MOT #13** 2020-10-08 11:41**MOT test number** 155205046888**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2019-05-11 09:59**MOT test number** 704215233762**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Small pin hole nearside front outer cv gaiter
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2019-05-09 10:58

**MOT test number**

662272299472

**Result****✗ Failed****Advice** Nearside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Outer sill covers obscuring some prescribed areas**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction sat nav holder (3.1 (a) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Under covers obscuring suspension components**Advice** Offside Rear Tyre worn close to legal limit/worn on edge uneven wear too 2mm (5.2.3 (e))**Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))**Advice** Engine bay covers obscuring some components**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #10** 2018-05-24 08:31**MOT test number** 195285940506**Result** ✓ Passed**MOT #9** 2018-05-03 14:41**MOT test number** 391881507747**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Advice** Nearside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #8** 2017-01-04 12:34**MOT test number** 824912592824**Result** ✓ Passed**Advice** Engine cover and under trays fitted**MOT #7** 2016-12-16 09:03**MOT test number** 830033966011**Result** ✗ Failed**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Engine cover and under trays fitted**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #6** 2016-01-07 16:19**MOT test number** 496915477992**Result** ✓ Passed**Advice** Under trays fitted

**MOT #5** 2016-01-07 16:19**MOT test number** 798761907585**Result** ✗ Failed

**Pass with rectification** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Under trays fitted

**Pass with rectification** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #4** 2016-01-06 13:51**MOT test number** 577721749867**Result** ✗ Failed

**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Engine covers and under trays fitted

**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**MOT #3** 2015-01-09 10:27**MOT test number** 985769705028**Result** ✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #2** 2014-01-04 10:05**MOT test number** 107304604021**Result** ✓ Passed**MOT #1** 2013-01-03 10:39**MOT test number** 719243003032**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
22 June 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	22 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-01-07
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2010-01-07	18 mi
Registration #2	2013-01-03	26.041 mi
Registration #3	2014-01-04	36.207 mi
Registration #4	2015-01-09	46.467 mi
Registration #5	2016-01-06	54.994 mi
Registration #6	2016-01-07	54.996 mi
Registration #7	2016-01-07	54.996 mi
Registration #8	2016-12-16	64.371 mi
Registration #9	2017-01-04	64.802 mi
Registration #10	2018-05-03	74.630 mi
Registration #11	2018-05-24	74.676 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi
Registration #17	2019-05-20	75.277 mi
Registration #18	2019-05-20	75.277 mi
Registration #19	2019-05-20	75.277 mi
Registration #20	2019-05-20	75.277 mi
Registration #21	2019-05-20	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D051208
---------------	---------