



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA EXCLUSIV CDTI 16V
Colour	Silver
Year of manufacture	2008
Top speed	135 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 2



Date	2022-02-23
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-15
Pictures	5
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-09
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	26
Total items failed	18

MOT #21	2023-09-09 10:36
MOT test number	742613711956
Result	✓ Passed
Next expiry date	2024-09-09

MOT #20	2023-09-09 06:57
MOT test number	711546496179
Result	✗ Failed
Fail	Nearside Front Windscreen wiper not working (3.4 (a))

MOT #19	2022-09-10 14:15
MOT test number	558310723732
Result	✓ Passed
Advice	Tyres wearing on the inside
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2021-08-14 07:34
MOT test number	323458849921
Result	✓ Passed



MOT #17	2020-08-15 09:19
MOT test number	958252790340
Result	✓ Passed
Advice	Steering column top bearing slightly worn (2.2.2 (b))

MOT #16	2019-09-05 10:53
MOT test number	810743249484
Result	✓ Passed
Advice	Slight play in steering adjustable column but locked in fixed position.

MOT #15	2019-09-05 08:20
MOT test number	719131263007
Result	✗ Failed
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Advice	Slight play in steering adjustable column but locked in fixed position.
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #14	2018-09-04 13:50
MOT test number	651666057398
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner and outer edge worn (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edge worn (5.2.3 (e))

**MOT #13**

2018-09-04 09:16

MOT test number

946214235428

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edge worn (5.2.3 (e))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edge worn (5.2.3 (e))**MOT #12**

2017-09-09 11:32

MOT test number

902760875804

Result**✓ Passed****Advice** Upper level components covers and undertrays fitted**Advice** 1x rear exhaust bracket broken**MOT #11**

2017-09-08 15:23

MOT test number

628844713214

Result**✗ Failed****Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Upper level components covers and undertrays fitted**Fail** Nearside Front coil spring broken (2.4.C.1a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** 1x rear exhaust bracket broken**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #10**

2016-08-31 14:04

MOT test number

949581566340

Result

✓ Passed

Advice Front wiper blades slightly smearing windscreen**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Engine management light staying on**Advice** Offside Front Tyre worn close to the legal limit 215/50/17 (4.1.E.1)**MOT #9**

2016-08-24 14:18

MOT test number

330292556744

Result

✗ Failed

Fail Nearside Headlamp aim too low (1.8)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Braking system leaking (3.6.A.1)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Advice** Engine management light staying on**Fail** Offside Headlamp aim too low (1.8)**Advice** Offside Front Tyre worn close to the legal limit 215/50/17 (4.1.E.1)**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Front wiper blades slightly smearing windscreen**MOT #8**

2015-08-07 11:30

MOT test number

508229015275

Result

✓ Passed

**MOT #7** 2015-08-07 11:30**MOT test number** 925379415221**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #6** 2014-08-06 11:06**MOT test number** 466058014206**Result** ✓ Passed**MOT #5** 2013-08-07 12:56**MOT test number** 399389613410**Result** ✓ Passed**MOT #4** 2012-08-07 12:21**MOT test number** 338350622253**Result** ✓ Passed**MOT #3** 2012-08-06 09:25**MOT test number** 939379912204**Result** ✗ Failed**Fail** Offside Rear coil spring incomplete (2.4.C.1a)**MOT #2** 2011-08-09 09:13**MOT test number** 527901621247**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



MOT #1	2011-03-11 14:21
MOT test number	237030571080
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
9 September 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	9 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 VU08VWV
Plate since	2019-03-29
Current registration	 VU08VWV
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-03-11
Last registration	2023-09-09
Complete history	See info



Registration #1	2008-03-11	9 mi
Registration #2	2011-03-11	41.257 mi
Registration #3	2011-08-09	45.498 mi
Registration #4	2012-08-06	53.303 mi
Registration #5	2012-08-07	53.303 mi
Registration #6	2013-08-07	62.377 mi
Registration #7	2014-08-06	71.215 mi
Registration #8	2015-08-07	79.333 mi
Registration #9	2016-08-24	86.958 mi
Registration #10	2016-08-31	86.958 mi
Registration #11	2017-09-08	94.108 mi
Registration #12	2017-09-09	94.108 mi
Registration #13	2018-09-09	94.108 mi
Registration #14	2019-09-09	94.108 mi
Registration #15	2020-09-09	94.108 mi
Registration #16	2021-09-09	94.108 mi
Registration #17	2022-09-09	94.108 mi
Registration #18	2023-09-09	94.108 mi
Registration #19	2024-03-29	94.108 mi
Registration #20	2024-03-29	94.108 mi
Registration #21	2024-03-29	94.108 mi
Registration #22	2024-03-29	94.108 mi
Registration #23	2024-03-29	94.108 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1428 kg
Max. allowed weight	2005 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	17390132