




report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Silver
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	M






Internet history

Entry 1

Date	2022-05-29
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2023-05-16
<b>MOT pass rate</b>	63 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	7
<b>Total advice items</b>	39
<b>Total items failed</b>	11

**MOT #19** 2022-05-17 15:45**MOT test number** 502860025006**Result** Passed**Next expiry date** 2023-05-16**Advice** Surface rust and black paint coating under the vehicle and on brake pipes and on some suspension components**Advice** Undertrays fitted obscuring inspection**MOT #18** 2021-11-10 10:14**MOT test number** 576846895422**Result** Passed**Advice** Nearside Front Tyre slightly damaged outer sidewall scuffed (5.2.3 (d) (ii))**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded behind plastic wheel arch cover (1.1.11 (c))**Advice** Fuel tank strap corroded

**MOT #17**

2021-11-05 12:36

**MOT test number**

429190770519

**Result****✗ Failed**

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded behind plastic wheel arch cover (1.1.11 (c))

**Advice** Fuel tank strap corroded

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**Fail** Headlamp levelling device inoperative corroded & broke (4.1.5 (a))

**Advice** Nearside Front Tyre slightly damaged outer sidewall scuffed (5.2.3 (d) (ii))

**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))

**MOT #16**

2020-10-30 15:06

**MOT test number**

887895853391

**Result****✓ Passed**

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #15**

2019-11-05 14:17

**MOT test number**

911091309261

**Result****✓ Passed**

**MOT #14** 2019-11-05 12:06**MOT test number** 364821508430**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #13** 2018-10-20 09:58**MOT test number** 168093125458**Result** ✓ Passed**MOT #12** 2018-10-19 14:44**MOT test number** 176352512271**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases front flex (6.1.2 (a))**MOT #11** 2017-11-07 13:17**MOT test number** 879483342149**Result** ✓ Passed**MOT #10** 2016-11-07 16:07**MOT test number** 831516739988**Result** ✓ Passed**Advice** Central Exhaust has a minor leak of exhaust gases back box blowing (7.1.2)

**MOT #9** 2016-11-05 10:49**MOT test number** 116832322378**Result** ✗ Failed**Fail** Offside Front Driver's door cannot be opened from inside the vehicle (6.2.B.1b)**Advice** Central Exhaust has a minor leak of exhaust gases back box blowing (7.1.2)**Fail** Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**MOT #8** 2015-03-28 12:37**MOT test number** 367037985004**Result** ✓ Passed**MOT #7** 2015-03-23 12:36**MOT test number** 848572285052**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #6** 2014-03-27 15:58**MOT test number** 637826884000**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2014-03-27 12:07**MOT test number** 666836684036**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Under-trays fitted obscuring some underside components**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Nearside Stop lamp not working (1.2.1b)**MOT #4** 2013-03-28 12:03**MOT test number** 216057383061**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2013-03-28 12:03**MOT test number** 878557983044**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #2	2012-03-21 10:06
MOT test number	197561182082
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2011-03-29 14:59
MOT test number	867648681097
Result	✓ Passed
Notice	O/S/F TYRE IS WORN TO 2/3/3mm
Notice	O/S/R TYRE IS WORN TO 3/2/3mm
Notice	REAR WIPER IS TORN
Notice	N/S/F TYRE IS WORN TO 3/4/2mm
Notice	N/S/R TYRE IS WORN TO 2/2/3mm



Tax & MOT check

X

Untaxed

Tax expired:  
21 April 2022

X

MOT

Expired:  
16 May 2023

Tax status	Expired at 21 April 2022
Days left	740 days too late
MOT expiry date	16 May 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	<b>ND08YMK</b>
Plate since	2019-03-29
Current registration	<b>ND08YMK</b>
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-28
Last registration	2022-05-17
Complete history	<a href="#">See info</a>



Registration #1	2008-03-28	13 mi
Registration #2	2011-03-29	32.133 mi
Registration #3	2012-03-21	46.357 mi
Registration #4	2013-03-28	61.544 mi
Registration #5	2014-03-27	75.029 mi
Registration #6	2014-03-27	75.029 mi
Registration #7	2015-03-23	85.527 mi
Registration #8	2015-03-28	85.642 mi
Registration #9	2016-11-05	103.853 mi
Registration #10	2016-11-07	103.853 mi
Registration #11	2016-11-07	103.853 mi
Registration #12	2016-11-07	103.853 mi
Registration #13	2016-11-07	103.853 mi
Registration #14	2016-11-07	103.853 mi
Registration #15	2016-11-07	103.853 mi
Registration #16	2016-11-07	103.853 mi
Registration #17	2016-11-07	103.853 mi
Registration #18	2016-11-07	103.853 mi
Registration #19	2016-11-07	103.853 mi
Registration #20	2016-11-07	103.853 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1850 mm
Height	1763 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2208 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	948835