





report date: 2024-03-28

General information

Make	MINI
Model	JOHN COOPER WORKS COOPER S
Colour	Red
Year of manufacture	2012
Top speed	138 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 4.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	55.4 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2022-12-23

Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-05-05
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #11	2024-04-18 15:05
MOT test number	739405092883
Result	✓ Passed
Next expiry date	2025-05-05
Minor Nearside Front Side repeater lens defective which has no effect on emitted light missing a cover (4.4.1 (b) (i))	

MOT #10	2024-04-18 08:33
MOT test number	369199764394
Result	× Failed
Minor Nearside Front Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))	missing a cover
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Side repeater not working (4.4.1 (a) (ii))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #9	2023-04-24 08:10
MOT test number	972736892216
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

189158329042

MOT #8 2022-05-06 10:19

MOT test number 203941606623

Result ✓ Passed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2021-05-06 09:54

MOT test number 137862715178

Advice Offside Front Tyre worn close to legal limit/worn on edge slight wear on edges (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge slight wear on edges (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge slight wear on inside edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

(i))

MOT test number

 MOT #6
 2020-09-07 10:42

 MOT test number
 697297544928

Result \(\sqrt{Passed} \)

MOT #5 2019-10-22 11:30

MOT #4 2018-10-24 11:20

MOT test number 720254886286

Result
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3		2017-10-05 12:13
MOT test	number	616361599527
Result		✓ Passed
Advice	Offside Front tyre worn on inner edge	
Advice	Nearside Front wheel damaged	

MOT #2	2016-10-19 14:00
MOT test number	571509227073
Result	✓ Passed
MOT #1	2015-10-15 10:27
MOT test number	151173518033
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	5 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

DA62BFX

report date: 2024-03-28

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-31
Last registration	2024-04-18
Complete history	See info



Registration #1	2012-10-31	11 mi
Registration #2	2015-10-15	16.891 mi
Registration #3	2016-10-19	22.015 mi
Registration #4	2017-10-05	27.066 mi
Registration #5	2018-10-24	31.498 mi
Registration #6	2019-10-22	35.194 mi
Registration #7	2020-09-07	38.064 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		D.207 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1205 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	2	
Number of seats CarCheck.co.uk	2 page 1	2/12