





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	PARTNER BLUE HDI S L1
Colour	White
Year of manufacture	2017
Top speed	98 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	75 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/11



## Internet history

Ent	- 100	1
EIII	. I V	-

Life y 1	
Date	2021-09-11
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-01-05
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	5

MOT #6		2023-12-15 08:22
MOT test numb	er	115457431557
Result		✓ Passed
Next expiry dat	te	2025-01-05
<b>Advice</b> Near	rside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))		
<b>Advice</b> Offsi	ide Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advice</b> Near	rside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offsic	de Registration plate lamp inoperative in the case of multiple lamps	or light sources (4.7.1 (b)

MOT #5	2022-12-15 14:18
MOT test number	426393435337
Result	✓ Passed
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cor  Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2022-12-15 12:27 254041523486 **MOT** test number Result × Failed Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Windscreen washer not working (3.5 (a)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail Registration plate lamp inoperative in the case of a single lamp or all lamps nearside and offside (4.7.1 (b) (ii)) **Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail **Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3	2022-01-06 09:29
MOT test number	498073908510
Result	<b>✓</b> Passed

MOT #2	2020-11-12 14:29
MOT test number	680406314772
Popult	4 Dassad

Passed Kesuit

**MOT #1** 2020-06-06 05:05

**MOT** test number 535077340664 Result ✓ Passed

**Advice** COVID-19 6 MONTH EXTENSION

MOT #2

CarCheck.co.uk page 4/11



#### Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	5 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11




report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

$\sim$		h:at	
- CJV	vner	misi	or

,		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
*******		
***************************************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-06-14
Last registration	2023-12-15
Complete history	See info



Registration #1	2017-06-14	24 mi
Registration #2	2020-11-12	43.474 mi
Registration #3		11.777 es
Registration #4	2022-01-06	51.879 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

D: 100	ensior	- C		ьь
		15 ~	wein	nı.

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1292 kg
Max. allowed weight	1940 kg

### Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBHB0040320

CarCheck.co.uk page 11/11