





report date: 2024-03-29

### General information

Make	FIAT
Model	PANDA DYNAMIC MULTIJET
Colour	Red
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	70 BHP
Max. torque	145 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	76.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-29

# Internet history

		1
ᆮ	HLIV	-

Lifety 1	
Date	2021-01-29
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

# MOT history

MOT expiry date	2024-12-15
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	29
Total items failed	4

MOT #15		2023-12-16 14:30
MOT test	number	294555539858
Result		✓ Passed
Next expi	ry date	2024-12-15
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Park brake cable deteriorated.	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Axle corroded.	

MOT #14		2023-12-16 14:30
MOT test	number	670329423042
Result		<b>×</b> Failed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Park brake cable deteriorated.	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Rear Axle corroded.	
Pass wit	h rectification Nearside Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice

Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice

Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT test number

Result

Advice Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

Pass with rectification Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

MOT #11 2021-12-07 16:06

**MOT test number** 928395060442

**Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement and offside front upper (5.3.4 (a) (i))

**Advice** Nearside Rear Coil spring corroded and offside rear (5.3.1 (b) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

**MOT #10** 2021-12-07 13:02

**MOT test number** 229673255126

Result X Failed

Fail Nearside Rear Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))

**Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement and offside front upper (5.3.4 (a) (i))

Fail Offside Rear Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))

**Advice** Nearside Rear Coil spring corroded and offside rear (5.3.1 (b) (i))

MOT #9 2020-11-27 15:15

**MOT test number** 685690879288

Result \square Passed

**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn on inner edge

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Windscreen wiper blade defective Both front wipers smearing (3.4 (b) (i))

Advice Rear Exhaust box corroded

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #8 2019-05-24 08:50

**MOT test number** 135120719724

Result \rightarrow Passed

**Advice** Rear Coil spring corroded bothsides (5.3.1 (b) (i))

Advice Rear exhaust backbox corroded

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #7	2018-05-31 07:47
MOT test number	662570280291
Result	✓ Passed
MOT #6	2017-05-16 10:09
MOT test number	990710579548
Result	<b>√</b> Passed
MOT #5	2016-05-16 09:55
MOT test number	190664863067
Result	<b>✓</b> Passed
MOT #4	2015-05-18 08:41
MOT test number	986118335145
Result	<b>✓</b> Passed
MOT #3	2014-05-16 08:46
MOT test number	206526334425
Result	<b>✓</b> Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #2	2013-06-05 08:54
MOT test number	688326353187

MOT test number	688326353187
Result	<b>✓</b> Passed
MOT #1	2012-06-06 13:05
MOT test number	415478852174
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	15 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13




report date: 2024-03-29

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
**************************************	
***************************************	
THE PERSON NAMED IN COLUMN TO THE PE	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	NIK ZIK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-15
Last registration	2023-12-16
Complete history	See info



Registration #1	2009-06-15	6 mi
Registration #2	2012-06-06	20.782 mi
Registration #3	2013-06-05	26.251 mi
Registration #4	2014-05-16	32.964 mi
Registration #5	2015-05-18	39.772 mi
Registration #6	2016-05-16	43.775 mi
Registration #7	2017-05-16	46.930 mi
Registration #8	2018-05-31	49.512 mi
Registration #9	2019-05-24	53.977 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

# Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	***
Video	see crash video



# Dimensions & weight

Width	1589 mm
Height	1578 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	935 kg
Max. allowed weight	1380 kg

# Additional information

Fuel tank capacity	35 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	4 pag	ge 13/13