



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA SE
Colour	Red
Year of manufacture	2005
Top speed	108 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-12-13
Pictures	16
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-01-23
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	32
Total items failed	25

MOT #24	2023-01-24 13:41
---------	------------------

MOT test number	580393583938
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-01-23
------------------	------------

- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill holed slight (5.3.6 (a) (i))
- Advice** Rear brake discs corroded
- Advice** Vehicle underside corroded and suspension components heavily corroded
- Advice** Gears crunching in gearbox when changing gear
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill holed slight (5.3.6 (a) (i))
- Advice** Rear brake discs back plates corroded
- Advice** Oil leak around gearbox area

**MOT #23**

2023-01-16 13:09

MOT test number

407904422439

Result**✗ Failed****Advice** Oil leak around gearbox area**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill holed slight (5.3.6 (a) (i))**Advice** Rear brake discs corroded**Advice** Vehicle underside corroded and suspension components heavily corroded**Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Gears crunching in gearbox when changing gear**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Fuel hose damaged fuel filler pipe holed (6.1.3 (c) (ii))**Advice** Front brake discs corroded**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive sill holed slight (5.3.6 (a) (i))**Advice** Rear brake discs back plates corroded**MOT #22**

2022-01-06 14:37

MOT test number

881049163062

Result**✓ Passed**

**MOT #21**

2022-01-05 15:53

MOT test number

550640214339

Result**✗ Failed**

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))

MOT #20

2021-01-30 11:00

MOT test number

472084709645

Result**✓ Passed**

- Advice** Offside Front slight binding

MOT #19

2020-02-01 12:19

MOT test number

263316164642

Result**✓ Passed**

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #18	2019-02-02 11:25
MOT test number	300635676149
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #17	2019-02-02 11:25
MOT test number	277162891955
Result	✗ Failed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Pass with rectification	Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Pass with rectification	Offside Front Service brake excessively binding (1.2.1 (f))
Pass with rectification	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #16	2018-01-31 12:07
MOT test number	554188378528
Result	✓ Passed

MOT #15	2018-01-31 09:12
MOT test number	235969274674
Result	✗ Failed
Fail	Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Front brake binding (3.7.B.1)
Advice	Offside Front Tyre worn close to the legal limit on limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Tyre worn close to the legal limit on limit (4.1.E.1)

**MOT #14** 2017-01-17 16:35**MOT test number** 121240814104**Result** ✓ Passed**MOT #13** 2017-01-17 09:29**MOT test number** 293163211758**Result** ✗ Failed

- Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

MOT #12 2016-02-05 15:56**MOT test number** 752064862532**Result** ✓ Passed

- Advice** Power steering component(s) has slight seepage from a component rack (2.3.3b)
- Advice** Nearside Front Tyre worn close to the legal limit 2.5mm (4.1.E.1)

MOT #11 2016-02-05 09:14**MOT test number** 939282358643**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit 2.5mm (4.1.E.1)
- Advice** Power steering component(s) has slight seepage from a component rack (2.3.3b)
- Fail** Offside Brake pipe excessively corroded rear section of front to rear (3.6.B.2c)

MOT #10 2015-01-31 09:36**MOT test number** 567621535011**Result** ✓ Passed

**MOT #9** 2014-01-21 15:50**MOT test number** 156591924059**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2013-01-30 14:58**MOT test number** 738630233029**Result** ✓ Passed**MOT #7** 2013-01-30 14:58**MOT test number** 667950233069**Result** ✗ Failed**Pass with rectification** Nearside Front All position lamps not working (1.1.A.3b)**MOT #6** 2012-01-18 15:23**MOT test number** 235018912094**Result** ✓ Passed**MOT #5** 2012-01-18 15:23**MOT test number** 529308212008**Result** ✗ Failed**Pass with rectification** Nearside Front Front suspension has a suspension lower ball joint securing nut not locked (2.5.B.1a)**Pass with rectification** Offside Front Front suspension has a suspension lower ball joint securing nut not locked (2.5.B.1a)**MOT #4** 2011-02-02 11:22**MOT test number** 249403331010**Result** ✓ Passed



MOT #3	2010-02-10 13:41
MOT test number	331261640037
Result	✓ Passed
MOT #2	2009-01-21 12:19
MOT test number	534341229056
Result	✓ Passed
MOT #1	2008-02-09 11:25
MOT test number	810490748074
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
22 February 2024

X

MOT

Expired:
23 January 2024

Tax status	Expired at 22 February 2024
Days left	68 days too late
MOT expiry date	23 January 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-03-30
Last registration	2023-01-24
Complete history	See info



Registration #1	2005-03-30	26 mi
Registration #2	2008-02-09	12.060 mi
Registration #3	2009-01-21	20.050 mi
Registration #4	2010-02-10	27.282 mi
Registration #5	2011-02-02	32.113 mi
Registration #6	2012-01-18	37.028 mi
Registration #7	2013-01-30	42.015 mi
Registration #8	2014-01-21	46.876 mi
Registration #9	2015-01-31	52.555 mi
Registration #10	2016-02-05	58.585 mi
Registration #11	2016-02-05	58.585 mi
Registration #12	2017-01-17	62.894 mi
Registration #13	2018-01-21	68.555 mi
Registration #14	2019-01-21	74.216 mi
Registration #15	2020-01-21	80.000 mi
Registration #16	2021-01-21	85.784 mi
Registration #17	2022-01-21	91.568 mi
Registration #18	2023-01-24	97.352 mi
Registration #19	2024-01-24	103.136 mi
Registration #20	2025-01-24	108.920 mi
Registration #21	2026-01-24	114.704 mi
Registration #22	2027-01-24	120.488 mi
Registration #23	2028-01-24	126.272 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1190 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	319019