





General information

| Make | VOLVO |
|---------------------|------------------|
| Model | V50 SE LUX D S40 |
| Colour | Blue |
| Year of manufacture | 2008 |
| Top speed | 127 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 134 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.998 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 153 g/km |
| CO2 label | G |







Internet history

Entry 1

Date

2021-10-15

Pictures

9

Listing price

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-06-06 |
|--------------------|------------|
| MOT pass rate | 93 % |
| MOT passed | 13 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 4 |

| MOT #14 | | 2023-06-07 11:03 |
|------------|--|------------------|
| MOT test n | number | 180070186922 |
| Result | | ✓ Passed |
| Next expir | y date | 2024-06-06 |
| Advice | Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #13 | | 2022-06-07 11:07 |
|-------------|---|------------------|
| MOT test nu | umber | 724489174462 |
| Result | | ✓ Passed |
| Advice | Low reading o/s/r parking brake, but meets legal requirements | |
| | | |

| MOT #12 | 2021-05-26 13:13 |
|-----------------|------------------|
| MOT test number | 804748369399 |
| Result | ✓ Passed |





| MOT #11 | 2021-05-25 11:10 |
|--|------------------|
| MOT test number | 304861995449 |
| Result | 🗙 Failed |
| Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) Fail Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) | |
| MOT #10 | 2020 05 26 12:20 |
| MOT #10 | 2020-05-26 12:20 |
| MOT test number | 903912090306 |
| Result | ✓ Passed |
| | |

| MOT #9 | 2019-05-09 11:46 |
|-----------------|------------------|
| MOT test number | 524921325263 |
| Result | ✓ Passed |

| MOT #8 | 2018-05-09 12:23 |
|-----------------|------------------|
| MOT test number | 429266883370 |
| Result | ✓ Passed |

| MOT #7 | 2017-05-03 13:59 |
|-----------------|------------------|
| MOT test number | 264302552568 |
| Result | ✓ Passed |
| | |

| MOT #6 | 2016-05-05 10:26 |
|-----------------|------------------|
| MOT test number | 819149348496 |
| Result | ✓ Passed |





| MOT #5 | | 2015-05-12 08:47 |
|----------|---|------------------|
| MOT test | number | 866272135105 |
| Result | | ✓ Passed |
| | | |
| MOT #4 | | 2014-05-10 12:48 |
| MOT test | number | 705520534126 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Brake pad(s) wearing thin (3.5.1g) | |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Advise exhaust box | |
| Advice | Offside Front Brake pad(s) wearing thin (3.5.1g) | |

| MOT #3 | 2013-04-08 15:21 |
|-----------------|------------------|
| MOT test number | 219418493061 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2012-04-05 17:01 |
| MOT test number | 315876792084 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2011-04-11 10:08 |
| MOT test number | 599281101150 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 January 2025 | ✓ MOT Expires: 6 June 2024 |
|--|-------------------------------------|
| Tax status | Valid until 1 January |
| Days left | 246 |
| MOT expiry date | 6 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Correct registration | |
| Plate since | |
| | |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2008-05-27 |
| Last registration | 2023-06-07 |
| Complete history | See info |



| Registration #1 | 2008-05-27 | 18 mi |
|--------------------------------------|------------|--|
| Registration #2 | 2011-04-11 | 25.262 mi |
| Registration #3 | 2012-04-05 | 39.397 mi |
| Registration #4 | 2013-04-08 | 55.506 mi |
| Registration #5 | 2014-05-10 | 72.325 mi |
| Registration #6 | 2015-05-12 | 80.155 mi |
| Registration #7 | 2016-05-05 | 84.185 mi |
| Registration #8 | 2017-05-03 | 86.452 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 est |
| Registration #11 | | 00.000 and |
| | | |
| Registration #12 | | 11.777 est |
| Registration #12 Registration #13 | | 11.577 est 11.577 est |
| - | | 11.577 est 11.577 est 11.577 est |
| Registration #13 | | 11.227 est 11.227 est 11.227 est 11.227 est |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| S0501 | |
| \$0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1457 kg |
| Max. allowed weight | 1940 kg |
| Additional information | |
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

| Number of axles | 2 |
|-----------------|--------|
| Engine number | 411629 |