





report date: 2024-03-29

### General information

Make	CITROEN	
Model	RELAY 35 HEAVY L4H3 ENTERPRISE BLUEHDI	
Colour	White	
Year of manufacture	2017	
Top speed	88 mph	
Gearbox	6 speed Manual	

# Engine & fuel consumption

Power	129 BHP	
Max. torque	350 Nm at 1.750 rpm	
Engine capacity	1.997 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	40.9 mpg	
Consumption extra urban	46.3 mpg	
Consumption combined	44.1 mpg	
CO2 emission	168 g/km	
CO2 label	Н	



CarCheck.co.uk page 1/11



## Internet history

### Entry 1

Date 2021-11-01

Pictures 3

Listing price <u>View report</u>







source: cargurus.co.uk

CarCheck.co.uk page 2/11



**MOT** history

Fail

MOT expiry date	2025-03-12
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	6
Total items failed	11

MOT #7	2024-03-11 11:45
MOT test number	830613953600
Result	✓ Passed
Next expiry date	2025-03-12

MOT #6	2023-03-11 16:59
MOT test number	699839167817
Result	✓ Passed

MOT #	5	2023-03-11 12:54
MOT te	est number	411423221651
Result		<b>×</b> Failed
Fail	Offside Outline marker lamp not working middle (4.2.1 (a) (ii))	
Fail	Electronic stability control warning lamp indicates a fault (7.12 (e))	
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

**Fail** Nearside Front Macpherson strut ball joint dust cover no longer prevents the ingress of dirt little play to (5.3.4 (b) (ii))

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

CarCheck.co.uk page 3/11



**MOT #4** 2022-03-11 15:23

MOT test number 327978164876

**Result** ✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #3 2021-03-03 14:56

**MOT test number** 319975290502

**Result** ✓ Passed

MOT #2 2020-03-13 10:54

**MOT test number** 621394869228

Result \( \sqrt{Passed} \)

Minor Nearside Windscreen damaged but not adversely affecting driver's view SMALL CHIP (3.2 (a) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1 2020-03-13 10:29

MOT test number 932603022027

Result X Failed

Fail Offside Position lamp not working MIDDLE SIDE POSITION LAMP (4.2.1 (a) (ii))

Fail Nearside Front Position lamp not working SIDE POSITION LAMP (4.2.1 (a) (ii))

**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Front Position lamp not working SIDE POSITION LAMP (4.2.1 (a) (ii))

Fail Offside Rear Position lamp not working SIDE POSITION LAMP (4.2.1 (a) (ii))

Minor Nearside Windscreen damaged but not adversely affecting driver's view SMALL CHIP (3.2 (a) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 4/11



### Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	12 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Owner History	
For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.	
********	
***************************************	
***************************************	
************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-05-19
Last registration	2024-03-11
Complete history	See info



Registration #1	2017-05-19	9 mi
Registration #2	2020-03-13	148.251 mi
Registration #3	2020-03-13	148.251 mi
Registration #4	2021-03-03	171.596 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi

More info >

CarCheck.co.uk page 10/11



## Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



# Dimensions & weight

Width	2050 mm
Height	2760 mm
Length	6363 mm
Wheel base	4035 mm
Kerb weight	2090 kg
Max. allowed weight	3500 kg

## Additional information

Fuel tank capacity	90
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	DYZZ4093541

CarCheck.co.uk page 11/11