





report date: 2024-03-28

General information

Make	BMW
Model	X6 XDRIVE30D M SPORT
Colour	Grey
Year of manufacture	2013
Top speed	138 mph
0 - 60 mph	7.6 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	241 BHP
Max. torque	540 Nm at 1.750 rpm
Engine capacity	2.993 сс
Cylinders	6
Fuel type	Diesel
Consumption city	32.5 mpg
Consumption extra urban	42.2 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	1



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-09-26

Pictures 23

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



KV63VBA

report date: 2024-03-28

MAGE	
NACAI	history
141()1	11151 OT V

MOT expiry date	2024-11-12
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #12	2023-11-13 13:02
MOT test number	737587075506
Result	✓ Passed
Next expiry date	2024-11-12

MOT #11	2022-10-31 13:02
MOT test number	265902394037
Result	✓ Passed

MOT #10	2021-09-28 11:23
MOT test number	362438836881
Result	✓ Passed

MOT #9	2021-09-27 14:23
MOT test number	754533723272
Result	X Failed

Advice Rear Tyre worn close to legal limit/worn on edge x2 (5.2.3 (e))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 3/12



MOT #8 2020-10-01 16:03

MOT test number 186748317768

Result ✓ Passed

Advice Rear tyres worn on inner edges and close to limits

Advice Vehicle needs tracking

Advice Offside front tyre cut in outer side wall

Advice Front tyres worn on inner edges

Advice Front track control arm bushes worn

MOT #7 2019-09-11 14:49

MOT test number 438050467735

Advice Central Rear Lower Oil leak, but not excessive slight leak of rear differential (8.4.1 (a) (i))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view small impact of gravel (3.2 (a) (i))

MOT #6 2019-09-11 10:50

MOT test number 447890759146

Result × Failed

Advice Central Rear Lower Oil leak, but not excessive slight leak of rear differential (8.4.1 (a) (i))

Fail Offside Rear Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view small impact of gravel (3.2 (a) (i))

MOT #5 2018-10-03 15:49

MOT test number 916591082571

CarCheck.co.uk page 4/12



Result

KV63VBA report date: 2024-03-28

× Failed

MOT #4 2018-09-19 09:10

MOT test number 564314955028

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #3 2018-08-22 10:40

MOT test number 123655908883

**

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2017-08-23 11:22

MOT test number 426731531642

Result
✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Emissions too low to register

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2016-09-15 09:28

MOT test number 633037410542

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Venicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1 Date Category Type Damage 2 Date Category



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



e which misterly	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report is	
manuscript Control of the Control of	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-09-21
Last registration	2023-11-13
Complete history	See info



Registration #1	2013-09-21	27 mi
Registration #2	2016-09-15	37.546 mi
Registration #3	2017-08-23	51.332 mi
Registration #4	2018-08-22	65.411 mi
Registration #5	2018-09-19	66.929 mi
Registration #6	2018-10-03	68.117 mi
Registration #7	2019-09-11	81.167 mi
Registration #8		77.777 46
Registration #9		77.777 46
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		77.777 es
Registration #13		

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1933 mm
Height	1776 mm
Length	4857 mm
Wheel base	2933 mm
Kerb weight	2075 kg
Max. allowed weight	2965 kg

Additional information

Fuel tank capacity	85 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2
Engine number 31158378