





### General information

Make	FIAT
Model	500X T-JET EASY PLUS
Colour	Grey
Year of manufacture	2017
Top speed	124 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power 118 BHP   Max. torque 214 Nm at 2.500 rpm   Engine capacity 1.368 cc   Cylinders 4   Fuel type Petrol   Consumption city 36.7 mpg   Some the type 186 - 225   Consumption extra urban 56.5 mpg   Consumption combined 47.1 mpg	
Max. torque 214 Nm at 2.500 rpm   Engine capacity 1.368 cc   Cylinders 4   Fuel type Petrol   Consumption city 36.7 mpg   186 - 225   225+	
Engine capacity 1.368 cc 121 - 140 E   Cylinders 4 141 - 165 166 - 185   Fuel type Petrol 166 - 185 186 - 225   Consumption extra urban 56.5 mpg 225+	
Cylinders 4 141 - 165   Fuel type Petrol 166 - 185   Consumption city 36.7 mpg 186 - 225   Consumption extra urban 56.5 mpg 225+	
Consumption city   36.7 mpg   186 - 225     Consumption extra urban   56.5 mpg   225+	Ē
Consumption extra urban56.5 mpg225+	H
	J
Consumption combined 47.1 mpg	L M
consumption combined 47.1 mpg	
CO2 emission 139 g/km	
CO2 label E	





# Internet history

Entry 1

Date Pictures 2022-01-05

19

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-01-05
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	9
Total items failed	1

МОТ #5	2023-01-05 16:26	
MOT test number	320914643558	
Result	✓ Passed	
Next expiry date	2024-01-05	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush debonding slightly (5.3.4 (a) (i))		
Minor Nearside Front Direction indicator lens defective which has no effect on emitted light lens cracked (4.4.1 (b) (i))		
Advice Offside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))		

MOT #4	2023-01-05 14:29
MOT test number	222101925202
Result	🗙 Failed
<b>Fail</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach outer sidewall (5.2.3 (d) (i))	n the ply or cords
Minor Nearside Front Direction indicator lens defective which has no effect on emitted (4.4.1 (b) (i))	l light lens cracked
Advice Offside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))	
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in excessive bush debonding slightly (5.3.4 (a) (i))	e movement rear





MOT #3	2022-01-06 10:44
MOT test number	670129085176
Result	✓ Passed
MOT #2	2021-02-23 09:11
MOT test number	505813979384
Result	✓ Passed
Advice Rear Brake disc worn, pitted or scored, but not seriously weaker	ned Both Rear (1.1.14 (a) (ii))
MOT #1	2020-02-26 10:16
MOT test number	507679081346
Result	✓ Passed





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
********	
*******	
**********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-03-01
Last registration	2023-01-05
Complete history	See info



Registration #1	2017-03-01	9 mi
Registration #2	2020-02-26	14.384 mi
Registration #3	2021-02-23	14.816 mi
Registration #4		11.117 esi
Registration #5		11.117 esi
Registration #6		11.117 esi
Registration #7		11.117 mi

More info >





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
\$0566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	74%
Safety systems	64%
Overall rating	79%
Video	see crash video



Dimensions & weight	
Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1350 kg
Max. allowed weight	1775 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/10

Number of axles	2
Engine number	2148185