



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-02-08
Pictures	13
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-10-14
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	27
Total items failed	7

MOT #14	2022-09-22 15:00
MOT test number	703656152485
Result	✓ Passed
Next expiry date	2023-10-14

MOT #13	2022-09-08 09:57
MOT test number	415116465803
Result	✗ Failed

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Central Rear Seat belt retracting mechanism defective Back row (7.1.2 (e))
- DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- DANGEROUS** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #12** 2021-10-14 08:02**MOT test number** 158608197791**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-10-08 13:44**MOT test number** 936735607321**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2020-10-07 10:05**MOT test number** 709254425240**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2019-10-15 13:19**MOT test number** 821402831090**Result** ✓ Passed**MOT #8** 2019-10-14 09:39**MOT test number** 231714931447**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 215/70/16 (5.2.3 (e))

**MOT #7** 2018-10-15 12:56**MOT test number** 496108956486**Result** ✓ Passed**MOT #6** 2017-12-04 12:01**MOT test number** 828433542524**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2017-12-04 12:01**MOT test number** 906788043957**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #4** 2016-11-25 10:59**MOT test number** 578769875336**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #3** 2015-10-29 12:16**MOT test number** 737128612900**Result** ✓ Passed**Advice** Front and rear brake discs worn



MOT #2	2014-11-17 15:29
MOT test number	169131124383
Result	✓ Passed
Advice	Nearside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)

MOT #1	2014-11-17 12:59
MOT test number	475291824345
Result	✗ Failed
Fail	Registration plate lamp not working (1.1.C.1d)
Fail	Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
Advice	Nearside Front Seat belt damaged but not affecting the operation of the belt (5.2.2a)
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
Fail	Parking brake lever has no reserve travel (3.1.6b)



Tax & MOT check

X

Untaxed

Tax expired:
31 January 2024

X

MOT

Expired:
14 October 2023

Tax status	Expired at 31 January 2024
Days left	88 days too late
MOT expiry date	14 October 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history


Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-11-25
Last registration	2022-09-22
Complete history	See info



Registration #1	2011-11-25	9 mi
Registration #2	2014-11-17	30.219 mi
Registration #3	2014-11-17	30.219 mi
Registration #4	2015-10-29	36.463 mi
Registration #5	2016-11-25	44.383 mi
Registration #6	2017-12-04	53.544 mi
Registration #7	2017-12-04	53.544 mi
Registration #8	2018-10-15	61.497 mi
Registration #9	2019-05-22	75.277 mi
Registration #10	2019-05-22	75.277 mi
Registration #11	2019-05-22	75.277 mi
Registration #12	2019-05-22	75.277 mi
Registration #13	2019-05-22	75.277 mi
Registration #14	2019-05-22	75.277 mi
Registration #15	2019-05-22	75.277 mi
Registration #16	2019-05-22	75.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CBB827791