



report date: 2024-03-29

General information

Make	CITROEN
Model	C2 HDI VTS
Colour	Black
Year of manufacture	2008
Top speed	120 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	260 Nm at 2.000 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	76.4 mpg
Consumption combined	64.2 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-13
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-30
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	24
Total items failed	5

MOT #17	2023-12-13 12:58
MOT test number	886438351905
Result	✓ Passed
Next expiry date	2024-12-30

MOT #16	2022-12-15 13:47
MOT test number	389044162548
Result	✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security sill (6.2.2 (d) (i))

MOT #15	2021-12-31 12:58
MOT test number	595981580309
Result	✓ Passed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2021-12-30 07:51
MOT test number	367438584419
Result	✗ Failed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt both sides outer clip (6.1.7 (g) (ii))

**MOT #13** 2020-12-14 13:21**MOT test number** 663953887678**Result** ✓ Passed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Spare wheel carrier loose**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #12** 2020-12-12 14:25**MOT test number** 672588251129**Result** ✗ Failed**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Spare wheel carrier loose**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecurely clipped (6.1.7 (g) (ii))**MOT #11** 2019-12-16 11:32**MOT test number** 132018848601**Result** ✓ Passed**MOT #10** 2019-04-12 13:54**MOT test number** 614241784405**Result** ✓ Passed**Advice** Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2018-05-16 14:33**MOT test number** 307909636043**Result** ✓ Passed**Advice** Outer sill covers fitted limiting inspection

**MOT #8**

2018-05-16 12:38

MOT test number

575712330795

Result**✗ Failed**

Fail Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Slight bind on off side rear brake

Fail Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Outer sill covers fitted limiting inspection

MOT #7

2017-05-17 09:52

MOT test number

786744335870

Result**✓ Passed**

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

MOT #6

2016-05-10 12:42

MOT test number

930302164118

Result**✓ Passed****MOT #5**

2015-05-15 15:38

MOT test number

195955835167

Result**✓ Passed**

**MOT #4** 2014-03-31 15:51**MOT test number** 909550094029**Result** ✓ Passed**Advice** Front Direction indicator slightly discoloured (1.4.A.2f)**Notice** Rear o.s brake slightly binding**Advice** Nearside Inner Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2013-03-22 14:14**MOT test number** 126071183445**Result** ✓ Passed**Advice** Nearside Inner Front Anti-roll bar has slight play in a ball joint (2.4.G.2)**MOT #2** 2012-03-30 11:52**MOT test number** 118320192098**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2011-03-17 14:58**MOT test number** 766706071026**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
30 December 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	30 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-04-03
Last registration	2023-12-13
Complete history	See info



Registration #1	2008-04-03	28 mi
Registration #2	2011-03-17	23.093 mi
Registration #3	2012-03-30	30.790 mi
Registration #4	2013-03-22	40.118 mi
Registration #5	2014-03-31	47.951 mi
Registration #6	2015-05-15	54.272 mi
Registration #7	2016-05-10	61.078 mi
Registration #8	2017-05-17	65.266 mi
Registration #9	2018-05-16	76.712 mi
Registration #10	2018-05-16	76.716 mi
Registration #11	2019-05-16	76.716 mi
Registration #12	2019-05-16	76.716 mi
Registration #13	2019-05-16	76.716 mi
Registration #14	2019-05-16	76.716 mi
Registration #15	2019-05-16	76.716 mi
Registration #16	2019-05-16	76.716 mi
Registration #17	2019-05-16	76.716 mi
Registration #18	2019-05-16	76.716 mi
Registration #19	2019-05-16	76.716 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1659 mm
Height	1474 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1122 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	JB853022866